

New Jersey Police Crash Investigation Report												Case Number 2018-00068411			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling westbound Route 88 in the area of Coolidge Dr. Vehicle #2 was traveling southbound Coolidge Dr. in the area of Route 88. While vehicle #2 was crossing over Route 88 from Collidge Dr. to Midstreams Rd. with the green traffic signal, vehicle #1 failed to stop for the red traffic signal colliding with the driver's side of vehicle #2. The impact of vehicle #1 into vehicle #2 propelled vehicle #2 off road right into a landscaping block wall in front of Joe's Towing/BP Gas Station. Driver #1 stated he ran the red light. Driver #2 stated he crossed over Rt. 88 with the green traffic signal. It should be noted, surveillance video of the area from Wine World corroborated driver #1's statement that he failed to stop for the red traffic signal. Driver #1 was found at fault for the accident.

146. Officer's Signature Daniel W Fogarty	147. Badge # 211	148. Reviewer James L Bartolucci	Badge # 183	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-------------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00068411

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Daniel W Fogarty

Officer's Signature

211

Badge Number