

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00069784			Page 2 of 4	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation revealed that vehicle 1 was backing out of a parking spot in the parking lot of 1453 State Highway 88. While vehicle 1 was backing, the driver side of its rear bumper struck the driver side rear fender of vehicle 2. Vehicle 2 was unoccupied, and parked perpendicular behind vehicle 1 in a non-designated parking spot. Upon arrival, vehicle 1 was moved back into its original parking spot, while vehicle 2 remained parked where it was. Both vehicles were operable, and no injuries were reported.

Driver 1 stated she returned home from grocery shopping and parked her vehicle facing east, in front of her apartment at 1451 State Highway 88. Driver 1 went inside to put her groceries away, and came back outside to drive elsewhere. While driver 1 was backing out of her parking spot, the rear end of her vehicle struck the rear fender of vehicle 2. Driver 1 stated she did not check to see if there was a vehicle behind her because there was no vehicle parked behind her when she returned home from grocery shopping. Driver 1 also stated vehicles are not permitted to be parked where vehicle 2 was.

Vehicle 2 was unoccupied when it was struck by vehicle 1, but driver of vehicle 2 stated he parked his vehicle facing south, outside of his friend's apartment at 1453 State Highway 88. Driver 2 reported he was picking up some friends, so did not park his vehicle in a designated parking spot while he went inside the residence to advise them he arrived. When driver 2 came back outside, he observed the rear bumper of vehicle 1

146. Officer's Signature Kyle W Patrick	147. Badge # 296	148. Reviewer Arthur D Rivaldo	Badge # 179	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2018-00069784

145 Crash Description

strike the rear fender of his vehicle.

Vehicle 1 sustained minor damage to its rear bumper, on the driver side. Vehicle 2 sustained minor damage to the rear fender, behind the wheel well, on the driver side.

Based on my investigation, I believe both drivers were at fault. Driver 1 was at fault for backing improperly and not paying attention to what was behind her vehicle. Driver 2 was also at fault for parking improperly in a fire zone, and not in a designated parking spot.

Kyle W Patrick

296

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00069784

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Kyle W Patrick

Officer's Signature

296

Badge Number