

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00070940			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was stopped at a stop sign on Burrsville Rd. waiting to merge onto RT 88. Vehicle 1 was stopped behind Vehicle 2. Vehicle 2 started forward but was forced to come to a stop again due to on coming traffic. Vehicle 1 started forward when Vehicle 2 started forward but failed to stop again and crashed into the rear of Vehicle 2.

Driver 1 admitted fault for the crash and stated when Vehicle 2 started forward he assumed it would continue onto RT 88. Driver 1 stated he started forward along with Vehicle 2, looked to his right to check for oncoming traffic, and failed to see that Vehicle 2 had come to a stop again. Driver 1 stated as he turned his head forward again he crashed into the rear of Vehicle 2.

No injuries were reported by either party and both vehicles were driven from the scene.

No motor vehicle summonses were issued.

146. Officer's Signature Daniel P Testa	147. Badge # 265	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station: —

Case No: 2018-00070940

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Daniel P Testa

Officer's Signature

265

Badge Number