

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00066357			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was approaching stop and go traffic on Rt 88 west bound approximately 750 feet west of Van Zile Rd (Near Laurelton Square Plaza). Vehicle #2 was slowing to stop when Vehicle #1 crashed into it's rear bumper. The crash caused that front air bag of Vehicle #1 to activate.

The driver of Vehicle #1 stated he noticed that Vehicle #2 was stopping to late and he pressed on his brake pedal. He added that his vehicle skidding on the wet blacktop and crashed into the rear of Vehicle #2.

The driver of Vehicle #2 stated she was slowing in traffic when crashed into by Vehicle #1. She added that the collision was hard enough to jolt her foot off of the brake pedal but that she was able to stop her vehicle prior to crashing into the vehicle in front of her.

The driver of Vehicle #1 complained of pain to his face due to the airbag. The driver of Vehicle #2 stated that she had head pain. Both drivers were checked by first aid but refused further medical attention on scene.

146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2018-00066357

144 Crash Diagram (NOT TO SCALE)



ROUTE 88



LAUREL
SQUARE



NOT TO SCALE

Robert F Scelfo

Officer's Signature

189

Badge Number