

NJTR-1 (Rev. 01/17)

| New Jersey Police<br>Crash Investigation Report |    |    |    |    |    |    |    |    |    |    |    | Case Number<br>2018-00066649 |    |                                                                                | Page 2 of 3 |  |
|-------------------------------------------------|----|----|----|----|----|----|----|----|----|----|----|------------------------------|----|--------------------------------------------------------------------------------|-------------|--|
|                                                 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94                           | 95 | Names & Addresses of Occupants<br><i>If Deceased, Date &amp; Time of Death</i> |             |  |
| E                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| F                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| G                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| H                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| I                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |
| J                                               |    |    |    |    |    |    |    |    |    |    |    |                              |    |                                                                                |             |  |

144. Crash Diagram



Show NORTH by Arrow  
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation revealed the following: Vehicle 1 was traveling west on Rt.88, when a deer ran into the roadway and struck Vehicle 1's passenger side door.

Driver of Vehicle 1 stated he was driving west on Rt.88 when a deer struck his passenger side door. The deer then ran of into the woods before police arrival. D#1 was not injured and had no complaint of pain on scene.

I observed moderate damage to the passenger side of Vehicle 1


|                                           |                     |                                |                |                                                                                                   |
|-------------------------------------------|---------------------|--------------------------------|----------------|---------------------------------------------------------------------------------------------------|
| 146. Officer's Signature<br>Cody Oliverio | 147. Badge #<br>286 | 148. Reviewer<br>Robert A Hine | Badge #<br>158 | 149. Case Status<br><input type="checkbox"/> Pending <input checked="" type="checkbox"/> Complete |
|-------------------------------------------|---------------------|--------------------------------|----------------|---------------------------------------------------------------------------------------------------|

New Jersey Police Crash Investigation Report  
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01  
Station:        Case No: 2018-00066649

144 Crash Diagram (NOT TO SCALE)

 Indicate North



Rt. 88



VAN ZILE RD

Cody Oliverio

Officer's Signature

286

Badge Number