

New Jersey Police Crash Investigation Report												Case Number 2018-00062653			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Crash investigation reveals a two vehicle, right angle crash. Vehicle 1 was stopped at a marked stop sign in the parking lot of 1608 Route 88 awaiting to turn left onto Route 88 W. Vehicle 2 was traveling west bound on Route 88 approaching the intersection of Route 88/Fort Street which is where the entrance/exit is located for 1608 Route 88.

As vehicle 2 was traveling west on Route 88, the driver of vehicle 2 stated vehicle 1 turned left onto Route 88 directly into the path of vehicle 2 causing the front end of vehicle 2 to crash into the left upper front of vehicle 1. The driver of vehicle 1 stated she observed vehicle 2 traveling west on Route 88 and believed she had enough time to make the left turn onto Route 88 from the lot of 1608 Route 88.

No injuries were reported and both vehicles sustained moderate damage. Vehicle 1 was towed from the scene by Glenn's Towing Co. and vehicle 2 was towed from the scene by Legacy Towing Co.. The driver of vehicle 1 is at fault for the crash and was issued a summons for 39:4-97 (1506-E18-3995).

146. Officer's Signature Thomas P Caulfield	147. Badge # 235	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station: —

Case No: 2018-00062653

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Thomas P Caulfield

Officer's Signature

235

Badge Number