

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00058805			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation concluded: Vehicle #1 and #2 were traveling on Rt. 88 (Eastbound) in the area of Old Squan Rd. Vehicle #2 was stopped attempting to make a left turn onto Old Squan Rd. when vehicle #1 struck Vehicle #2 in the rear.

Driver of Vehicle #1 advised he was traveling on Rt. 88 when the accident occurred. Driver of Vehicle #1 relayed he did not know what happened.

Driver of Vehicle #2 advised he was stopped on Rt. 88 attempting to make a left turn onto Old Squan Rd. when Vehicle #1 struck his vehicle in the rear.

146. Officer's Signature James M Albanese	147. Badge # 257	148. Reviewer James J Kelly	Badge # 233	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00058805


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



OLD SQUAN RD.

RT. 88



James M Albanese

Officer's Signature

257

Badge Number