

New Jersey Police Crash Investigation Report												Case Number 2021-00066281			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

My investigation revealed the following:

Vehicle 1 was traveling East on Route 88 approaching the intersection with Burnt Bridge Ave. A deer emerged from a wooded area adjacent to Burnt Bridge Ave. as vehicle 1 was reaching the intersection. The deer subsequently crossed into the path of vehicle 1 and was struck. Driver 1 was uninjured and the vehicle suffered damage to the driver's side headlight and bumper area.

Driver 1 stated he was traveling East on Route 88. He observed the deer enter his path from the left but was unable to do anything to avoid the crash.

Based upon the above circumstances I find that the deer caused the crash and driver 1 was unable to avoid the animal.

146. Officer's Signature Anthony Barlowski	147. Badge # 284	148. Reviewer Keith Prendeville	Badge # 223	149. Case Status ☐ Pending ☒ Complete
---	---------------------	------------------------------------	----------------	---


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00066281

144 Crash Diagram (NOT TO SCALE)


○ Indicate
North

Burnt Bridge Ave.



Not To Scale

P.O.I.



Route 88

Anthony Barlowski

Officer's Signature

284

Badge Number