

96	Page 1 of 4 ☐ Fatal		New Jersey Police Crash Investigation Report															☒ Reportable ☐ Non-Reportable ☐ Change Report			118a																													
05	1. Case Number 2021-00061695										10. Crash Occurred On: 1872 RT 88										11. Speed Limit - - - - -			12. Route No. Suffix 13. Milepost			08																							
01	2. Police Dept. of Brick Police Code 01										Road Name Dir																02																							
03	3. Station/Precinct										☐ At Intersection with ☐ N ☐ E ☐ Feet ☐ S ☐ W ☐ Miles										18. Speed Limit - - - - -						119a																							
09	4. Date of Crash mm dd yy										5. Day of Week Su M Tu W Th F Sa										6. Time (use 2400 hrs.)										7. Municipality Code			8. Total Killed			9. Total Injured			119b										
01	0 9 1 1 2 1										Th F Sa										1 9 1 6										1 5 0 6			-			-			120a										
05	23. Veh. # RRG13681820										24. Policy No. 13736										25. NJ Ins. Code										53. Veh. #			54. Policy No.			55. NJ Ins. Code			120b										
02	☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run										☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run																			121a																				
01	26. Driver's First Name Ernest Initial C Last Name Roy										29. Sex M										56. Driver's First Name										57. Driver's First Name			58. Driver's First Name			59. Sex			121b										
01	27. Number & Street 419 BUTLER AVE										57. Number & Street																						122																	
01	28. City Lancaster State PA Zip 17602										58. City																						02																	
01	30. Eyes 0 4 DL Class A Restrictions - - - - - Endorsements - - - - -										31. State PA										60. Eyes - - - - - DL Class - - - - - Restrictions - - - - - Endorsements - - - - -										61. State						123													
11	32. Driver's License Number 2 9 8 4 3 9 0 2										33. DOB mm dd yy 0 9 0 6 6 0										34. Expires mm yy 0 9 2 4										62. Driver's License Number										63. DOB mm dd yy			64. Expires mm yy			124			
02	35. Owner's First Name Initial Last Name										65. Owner's First Name Initial Last Name																						11																	
02	☐ Same as Driver Swift Transporation Co of Arizona llc										☐ Same as Driver																						125																	
02	36. Number & Street 6500 W INDUSTRIAL HWY										66. Number & Street																						126a																	
25	37. City Gary State IN Zip 46406										67. City																						56																	
02	38. Make Freightline 39. Model 40. Color WT 41. Year 2019 42. Plate No. 2531252 43. State IL										68. Make 69. Model 70. Color 71. Year 72. Plate No. 73. State																						126b																	
02	44. VIN 3 A K J H H D R 4 K S K J 0 3 0 0 45. Expires 09/21										74. VIN										75. Expires												56																	
02	46. Vehicle Removed to:										76. Vehicle Removed to:																						126c																	
02	☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☒ Left at Scene ☐ Towed Impounded										☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded																						56																	
03	47. Authority ☐ Owner ☒ Driver ☐ Police										77. Authority ☐ Owner ☐ Driver ☐ Police																						127a																	
02	48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - - % ☐ Pending										49. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class Placard No.										78. Alcohol Drug Test Given: ☐ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - - % ☐ Pending										79. Hazardous Material ☐ None ☐ On Board ☐ Spill Hazard Class Placard No.																			127b
02	50. Carrier No. ☒ USDOT 0 5 4 2 8 3 ☐ None ☐ MC/MX										51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☒ ≥ 26,001 lbs.										80. Carrier No. ☐ USDOT ☐ None ☐ MC/MX										81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.																			127c
02	52. Motor Carrier or Government Entity Swift Transportation Co of Arizona llc										82. Motor Carrier or Government Entity																						127d																	
02	Number & Street 2200 S 75TH AVE										Number & Street																						127e																	
02	City Phoenix State AZ Zip 85043										City																						128																	
02	135. Damage to Other Property ☒ Yes (If Yes, describe) Walmart. 1872 RT 88, BRICK TOWNSHIP, NJ 08724 broken curb/ damaged grass ☐ No																																56																	
02	Oper. 136. Charge										137. Summons No.										Oper. 138. Charge										139. Summons No.													11						
02	Oper. 140. Charge										141. Summons No.										Oper. 142. Charge										143. Summons No.													11						

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	-	61	M	-	-	-	11	04	-	-	Ernest C Roy 419 BUTLER AVE Lancaster PA 17602
B														
C														
D														

New Jersey Police Crash Investigation Report												Case Number 2021-00061695			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On 9/11/2021 at 1916 hours, I responded to the Walmart parking lot for a single tractor trailer crash.

The driver of vehicle 1 stated there was traffic on the access road blocking him from making the right hand turn.

The driver of vehicle 1 continued by stating he proceeded to back up, drive through the parking stalls, and attempted to make his right hand turn. The driver of vehicle 1 stated his driver's front tire of his tractor trailer went up on the curb, and onto the grass, causing him to slide down the embankment into the Wendy's parking lot.

I observed the trailer of the vehicle striking the curb causing the curb to break free. There was also visible signs of damage to the grass on the embankment caused by vehicle 1. Tow trucks from Joe's Service center, along with Glen's towing arrived on scene to free the vehicle from the embankment. The tow trucks where able to free the tractor trailer and it was left at the scene in a better location in the Walmart parking lot.

Truck: Freightliner Cascadia

146. Officer's Signature Andrew Emil Bajor	147. Badge # 305	148. Reviewer Erik A Olsen	Badge # 185	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01

Station: Case No: 2021-00061695

145 Crash Description

Trailer registration: Oklahoma BA7376

My department issued body worn camera was activated during this incident.

Andrew Emil Bajor

Officer's Signature

305

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2021-00061695

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Not To Scale

WENDY'S

GRASS EMBANKMENT

WALMART PARKING LOT

Andrew Emil Bajor

Officer's Signature

305

Badge Number