

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00053532			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was making a left turn from Midstreams Road onto Route 88, to travel east on Route 88. Vehicle 2 was traveling south on Coolidge Drive in the area of Route 88. Vehicle 1 failed to yield the right of way to Vehicle 2 in the intersection, causing the crash.

Driver 1 stated they were making a left turn from Midstreams Road onto Route 88, to travel east on Route 88. Driver 1 stated it appeared that Vehicle 2 had not started traveling after the light change, and was allowing him to make the left turn. Driver 1 started to make the left turn while Vehicle 2 was traveling into the intersection. Driver 1 struck Vehicle 2 in the intersection.

Driver 2 stated they were traveling on Coolidge Drive in the area of Route 88. Driver 2 entered the intersection to continue onto Midstreams Road. Driver 2 stated Vehicle 1 made the left turn in the intersection, striking her vehicle.

Both vehicles were moved prior to my arrival. There were no reported injuries on scene. Vehicle 2 was towed from the scene by Surfside Towing.

146. Officer's Signature Christopher R Joaquim	147. Badge # 271	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station:

Case No: 2018-00053532

144 Crash Diagram (NOT TO SCALE)



Christopher R Joaquim

271