

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00050054			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Both vehicle were stopped in traffic on the ramp from Route 70 east bound waiting to go onto Olden Street.

Driver #1 stated they were stopped waiting for the red light when she began looking for her ring in the center console. Upon looking for the ring, she leaned over the console and believes her foot came off the brake pedal which allowed her vehicle to roll forward into Vehicle #2.

Driver #2 stated he was stopped at the red light when he was struck fro behind.

Based on my observations and statements made by both drivers, I determined Driver #1 to be at fault for the crash.

146. Officer's Signature Joseph W McGrath	147. Badge # 277	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00050054

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Joseph W McGrath

Officer's Signature

277

Badge Number