

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00052812			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicles 1 and 2, were both traveling east on RT 88 stopped at a red traffic signal. While stopped, the driver of vehicle 1 attempted to grab her purse from the passenger seat, during which time her foot slipped from the brake, causing vehicle 1 to strike vehicle 2.

Vehicles 1 and 2 sustained minor damage. The driver of vehicle 2 had a complaint of pain, but refused medical treatment.

The driver of vehicle 2 stated, "I was stopped in traffic, when I felt a vehicle crash into my rear bumper."

The driver of vehicle 1 stated, "My foot slipped off the pedal and I bumped the car slightly."

Upon completion of my investigation, vehicle 1 was to be found at fault.

146. Officer's Signature John C Rotondo	147. Badge # 252	148. Reviewer Arthur D Rivaldo	Badge # 179	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:



Case No: 2018-00052812

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



NOT TO SCALE



John C Rotondo

Officer's Signature

252

Badge Number