

2-1

7

2 Stallion Drive

96-350

3

**MARLBORO TWP.
CONSTRUCTION DEPT.**

Construction Official
WM.G. NEWMAN



**CONSTRUCTION
PERMIT**

Date Issued

Control #

Permit #

4/8/96
96-350

IDENTIFICATION Block 226 Lot 2

Work Site Location 3 Stockton Drive

Contractor RTW Consultants

MARLBORO

Address 198 Sycamore Court

Owner in Fee MICHAEL TANNENHOLZ

Howell N.J. 07731

Address SAME

Tele. (908) 294-9126

Tele. _____

Lic. No. or Bldrs. Reg. No. _____ Exp. Date _____

Federal Emp. No. _____

or Social Security No. 136-42-5525

is hereby granted permission to perform the following work:

☐ BUILDING ☐ PLUMBING ☐ OTHER _____

☐ ELECTRICAL ☐ FIRE PROTECTION _____

☐ ELEVATOR DEVICES _____

DESCRIPTION OF WORK: ABANDONMENT OF (1) - 530

GAL. U.S.T. Heating oil TANK.

NOTE: If construction does not commence within one (1) year of date of issuance, or if construction ceases for a period of six (6) months, this permit is void.

Estimated Cost of Work \$ 675.00

[Signature]

PAYMENTS (Office Use Only)	
Building	<u>50-</u>
Electrical	_____
Plumbing	_____
Fire Protection	_____
Elevator Devices	_____
Other	_____
DCA Training Fee	_____
Cert. of Occ.	_____
Other	_____
Total	<u>50- 50-</u>
Check No.	<u>1766</u>
Cash	_____
Collected By:	<u>[Signature]</u>

**MARLBORO TWP.
CONSTRUCTION DEPT.**



**BUILDING
SUBCODE
TECHNICAL SECTION**



Date Received 4/8/96
Date Issued _____
Control # _____
Permit # 96-350

A. IDENTIFICATION—APPLICANT: COMPLETE ALL APPLICABLE INFORMATION. WHEN CHANGING CONTRACTORS, NOTIFY THIS OFFICE. CALL UTILITY DIG NO: 1-800-272-1000.

Block 226 Lot 2
Work Site Location 3 STOCKTON DRIVE
MARLBORO
Owner in Fee MICHAEL TANNERHOLZ
Address SAME
Tele. _____
Contractor RTW CONSULTANTS
Address 198 SYCAMORE COURT
HOWELL N.J.
Tele. (908) 294-9126
Lic. No. or Bldrs. Reg. No. _____
Federal Emp. No. _____ or Social Security No. _____

JOB SUMMARY (Office Use Only)

PLAN REVIEW	Date	Initial	INSPECTIONS	Dates (Month/Day)			
☐ No Plans Req.	_____	_____	Type:	Failure	Failure	Approval	Initial
☐ All	_____	_____	Footing	_____	_____	_____	_____
☐ Footing	_____	_____	Foundation	_____	_____	_____	_____
☐ Foundation	_____	_____	Slab	_____	_____	_____	_____
☐ Frame	_____	_____	Frame	_____	_____	_____	_____
☐ Other _____	_____	_____	Insulation	_____	_____	_____	_____
Joint Plan Review Required:	_____	_____	Finishes:	_____	_____	_____	_____
☐ Elec. ☐ Plumb. ☐ Fire	_____	_____	Energy	_____	_____	_____	_____
SUBCODE APPROVAL	_____	_____	Mechanical	_____	_____	_____	_____
☐ CO ☐ CCO ☐ CA	_____	_____	TCO	_____	_____	_____	_____
Date: _____	_____	_____	Other	_____	_____	_____	_____
Approved By: _____	_____	_____	Final	_____	_____	_____	_____

B. BUILDING CHARACTERISTICS

Use Group Present _____ Proposed _____
Constr. Class Present _____ Proposed _____
No. of Stories _____
Height of Structure _____ Ft.
Area—Largest Floor _____ Sq. Ft.
Total Bldg. Area/All Floors _____ Sq. Ft.
Volume of Structure _____ Cu. Ft.
Total Land Area Disturbed _____ Sq. Ft.

Est. Cost of Bldg. Work:

1. New Bldg. \$ _____
2. Alteration \$ \$675.00
3. Total (1+2) \$ \$675.00

C. CERTIFICATION IN LIEU OF OATH

I hereby certify that I am the (agent of) owner of record and am authorized to make this application.

Signature Robert J. Wojnowski

**D. TECHNICAL SITE DATA
DESCRIPTION OF WORK**

ABANDONMENT of
550 GAL. Heating oil
TANK.

TYPE OF WORK:

- ☐ New Building
☐ Addition
☐ Alteration
☐ Roofing
☐ Siding
☐ Other _____
☒ Demolition
☐ Miscellaneous
☐ Fence _____ Height _____
☐ Sign _____ Sq. Ft. _____
☐ Pool
☐ Elevator
☐ Asbestos Abatement
☐ Other _____

(Office Use Only)

FEE

\$ _____

Paid ☐ Check # _____
Collected by: _____

Administrative Surcharge \$ _____
Minimum Fee \$ _____
DCA TRAINING FEE \$ _____
TOTAL FEE \$ 50 -