



APR 12 2018

DEP #13892
DOT #964169
HIC #13VH04019900

732-303-8472

**New Jersey Department of Environmental Protection
Individual Subsurface Sewage Disposal System Inspection Report**

Inspection Overview - Preliminary system information - Inspection of treatment tanks - Absorption system inspection - Disposal/conveyance system assessment - Identification of any alternative technology approved Components -Requires additional inspection		Inspection form is not applicable to cesspools, privies, outhouses, pit toilets or latrines. Identification of such units shall be reported to the administrative authority	
CLIENT INFO	Client Name:	SYSTEM LOCATION	Inspection Company: Atlas Septic Inc
	Different from owner?		Inspector Name: Bobby
	Client Address:		Inspection Date: 4-10-18
			Site Address: 480 Randolph Rd
			Time in: 7:45
			Time out: 2:00
	Contact Method:		Municipality: Freehold County: Monmouth
	Cell:		Block(s): 33.15 Lot(s): 6
Work tel:	Was GPS used? YES		
Email:			

Preliminary Information:		Yes/No
Weather: Cloudy 45°	Is there a site plan or septic map available?	NO
Last Precipitation: 4-3-18	Is the dwelling currently being occupied?	YES
Age of system: House Built: 1985	If so, how many occupants?	N/A
Type of dwelling? Residential		
Describe: Single Family	If no, date last occupied?	
Number of Bedrooms: 3		
How many systems are being inspected? 1	If there is a washing machine, is it connected to a separate gray water disposal system?	NO
List any commercial activities or high impact hobbies:	Is the dwelling free of additional gray water systems?	YES
N/A	Is the dwelling free of garbage disposal systems?	NO
Describe prior problems and/or repair history including soil fracturing or use of chemical activities. Include dates and explain why the remedial measures have been applied to the system:	Is dwelling free of sump pump discharges to the system?	YES
N/A	Is dwelling free of any historical sanitary sewage back ups into the structure?	YES
	Does all sanitary sewage enter the septic system and no types of sewage bypass exist?	YES
Date file review requested with administrative authority:	Septic Tank Pumping:	
3-28-18	Is the septic tank pumped regularly?	N/A
	Frequency:	N/A
	Date of last pumping:	N/A
	Was file review completed prior to inspection?	NO
Comments:	If no, explain why below: did not get	

Treatment Tank:			Yes/No
		Main tank lid opened for inspection?	YES
Type of system being inspected? * Septic Tank		Liquid level below the tank's inlet invert?	YES
		Liquid level below the tank's outlet invert?	NO
Name the material of the system? Concrete		Treatment tank pumped for this inspection?	YES ✓
Approximate Treatment Tank Volume: 1500		Are all portions of the tank(s) clear of structures like a deck or a driveway?	YES
Evaluate the conditions of tank below:		Is the area clear of evidence that sanitary sewage has surfaces above the treatment tank?	YES
	<i>Satisfactory, Unsatisfactory, or N/A</i>	Does water flow unimpeded from the treatment tank?	NO
Tops and lids	SATISFACTORY	Is an effluent filter a part of the system?	NO
Inlet baffle	SATISFACTORY	If yes, does it appear properly maintained?	
Outlet baffle	SATISFACTORY	Are there any other types of accessory units present?	NO
Cracks or Leaks	SATISFACTORY		
Sanitary sewage flow from structure	SATISFACTORY	Depth to top of tank: 32'	
		Depth to top of tank access: 3"	
* Cesspools, privies, outhouses, latrines and pit toilets are not systems and must not be inspected in accordance with this protocol. If a cesspool, privy, outhouse, latrine or pit toilet is used for onsite wastewater disposal, the administrative authority shall be notified.			
Comments:			
Absorption Area:			Yes/No
Name the type of absorption system? (disposal bed, disposal trench, seepage pit, mounded) Disposal Bed			
Was the absorption system located?			YES
If no, explain below in Comments section.			
Are inspection ports present?			NO
If yes, how many?			
Were the inspection ports checked?			
Was a separate probe dug in the absorption area to confirm the observations in the inspection ports?			YES
Is the area of the absorption system free of sanitary sewage odors?			YES
Does sanitary sewage flow from the treatment tank to the absorption system without flowing back?			(YES)
Is the area above or near any of the system components free from visible signs of effluent or sanitary sewage?			YES
Are the areas at or near the inlet invert of any absorption area component free of visible signs of sewage or effluent?			YES
Are areas above or near system components free of lush vegetation?			YES
If exposed, is the distribution box in satisfactory condition?			(YES)
If not exposed, explain why not:			
Is the area directly over any part of the absorption system free of any evidence of large objects (such as boulders, sheds, landscaping, boats, cars, tractors, pools)?			YES
**All levels observed must be included in report			
Comments: Pipe from tank to D- box has standing water. D- Box has a lot of paper and sludge. Recommended hydraulic test. No sludge or water found in disposal bed. There is a ball valve to switch from one system to the other.			

Dosing or Pump Tank:	Yes, No, N/A
1. Does the system contain a pump tank?	NO
2. Is the pump operating?	N/A
3. Do the alarm(s) on the pump work?	N/A
4. Is the pump elevated above the tank floor?	N/A
5. Is the lid in satisfactory condition?	N/A
6. Is the tank in satisfactory condition?	N/A
7. Is the tank free of accumulated solids?	N/A
Summary:	Satisfactory, Satisfactory with Concerns, Unsatisfactory, Requires Additional Investigation, High Water or N/A
Identification of cesspool, privy, outhouse, latrine and pit toilet	N/A
Condition of the treatment tank(s)	SATISFACTORY
Condition of the conveyance and pump system(s)	N/A
Condition of the absorption area(s)	SATISFACTORY
Condition of any accessory components	SATISFACTORY

Comments: Pipe from tank to D- Box hole standing water in it. Recommend hydraulic test

Health Department Reporting:

Note if any of the following conditions were observed during the inspection:

- ☐ 1. Ponding or breakout of sanitary sewage or effluent onto the surface of the ground
- ☐ 2. Seepage of sanitary sewage or effluent into portions of buildings below ground
- ☐ 3. Backup of sanitary sewage into the building served which is not caused by physical blockage of the internal plumbing
- ☐ 4. Any manner of leakage observed from or into septic tanks, connecting pipes, distribution boxes and other components that are not designed to emit sanitary sewage or effluent.

Pursuant to N.J.A.C. 7:9A-3.4 notification of any observation that is consistent with a condition noted above should be reported to the administrative authority within 24 hours after the observation. Regardless of the observations made, a copy of this report should be provided to the administrative authority within 10 days after the issuance of this report.

If encountered, describe all observed noncompliant conditions encountered during this inspection:


Customer Authorization:

I authorize Atlas Septic Inc. to enter the above listed property for the purpose of performing a subsurface sewage disposal system inspection. I authorize Atlas Septic Inc. to expose parts of the system required, to determine location and condition. I understand that Atlas Septic Inc. relies on the information supplied by the owner(s) of the listed property or their agent and the administrative authority in the evaluation of the subsurface sewage disposal system. I authorize Atlas Septic Inc. to provide this form to all parties as required.

Customer Signature: _____ Printed Name: _____ Date: _____
Authorized Person

Inspector Signature: _____ Printed Name: Bobby Date: 4-10-18

Approximate System Location



FREEHOLD AREA
HEALTH DEPARTMENT

-SERVING-
FREEHOLD TOWNSHIP FREEHOLD BOROUGH

Margaret Jahn, MS, MPH
Director

Municipal Plaza Schanck Road
Freehold, New Jersey 07728-3099
732-294-2060

PROPERTY CERTIFICATION

DATE: 5/9/18 BLOCK: 33.15 LOT: 6

LOCATION: 480 Randolph Rd

OWNER (NEW/PREVIOUS): Toto

☐ An examination of the well water based upon the New Jersey Private Well Testing Act was taken on . Results indicate that the well water is safe for human consumption.

☒ Public community water supply - Monitored regularly


☐ A Registered Environmental Health Specialist has reviewed the onsite system inspection results performed by on . At this time, there are no obvious indications of malfunction or non-compliance with N.J.A.C. 7:9A.

☒ A Registered Environmental Health Specialist has reviewed the onsite system inspection results performed by Atlas Septic on 4/10/18. There were one or more items that were not in compliance with N.J.A.C. 7:9A that have been corrected to the satisfaction of the Health Department.

☐ A Registered Environmental Health Specialist has reviewed the onsite system inspection results performed by on . There were one or more items that are not in compliance with N.J.A.C. 7:9A. We are willing to grant a limited approval for a Temporary Certificate of Occupancy until compliance is attained.

If you have any questions regarding the interpretation of the onsite system inspection report and/or this certification, please call the Health Department at (732) 294-2060.

DATE SEPTIC PUMPED: 4/10/18


Registered Environmental Health Specialist

Copy to Building Department.