

Jacket Search Results New Construction Project

Search results for: Block equals 29.1 AND Lot equals 12

TACO VIEW 1-3 of 3

Received	Project Name	Permit Number	Certificate	Block	Lot	Proposed Work Site at:	Description of Work	Violation	Permit Fees Due	Zoning Total Due	Permit Status	Workflow Status
01/27/2004	10634 - 80 ROUTE 537	20040050		29.1	12	80 ROUTE 537	OIL TO GAS CONVERSION/ BOILER AND HOT WATER HEATER		\$0.00	\$ 0.00	Permit 20040050 01/27/2004	Status Issued Open
<i>Plumbing + Electric inspections done Fire Inspection - OPEN</i>												
08/27/1996	3530 - 80 ROUTE 537	19960473		29.1	12	80 ROUTE 537	WINDOW REPLACEMENT		\$0.00	\$ 0.00	Permit 19960473 08/27/1996	Status Issued Open
<i>(Permit Expired)</i>												
09/26/1995	2732 - 80 ROUTE 537, WEST	19950793		29.1	12	80 ROUTE 537, WEST	WINDOW REPLACEMENT		\$79.00	\$ 0.00	Permit 19950793 09/26/1995	Status Issued Open
<i>(Permit Expired)</i>												

Copyright © Jungle Lasers Inc. All rights reserved.

1990-362 Deck - Records Incomplete
1990-418 Electrical Alterations - Permit Closed

NOTE: 131 Route 537 was previously
80 Route 537