



Construction

Property Summary

[Portal](#) | [Refresh](#) | [Open All](#)
| [Close All](#)

Owner: CROSBY, CHARLENE M
Location: 23 MULBERRY COURT UNIT D
Block: 62.01
Lot: 23.04
Lead Parcel: Yes
Qualifier:

▼ About the Owner...

▼ About the Property...

▼ About the Taxes...

▼ Property Item...

▲ Construction...

Applications... [Expand](#)

<u>Permit Issue Date</u>	<u>Control Number</u>	<u>Permit Number</u>	<u>Work Type</u>	<u>Subcodes</u>	<u>Status</u>	<u>Close Date</u>	<u>Certificates</u>	<u>Total Cost</u>	<u>Agent</u>
	BR-23-00347		Alteration	P E M	Pickup			\$17,250	OCEANSIDE SERVICE
HVAC REPLACEMENT									
 6/16/1999		99157	Alteration	P	CA and Close Date Issued	6/17/1999	CA	\$800	

Would you like to add a application to this parcel? [Yes](#)

Inspections... [Expand](#)

<u>Date</u>	<u>Control Number</u>	<u>Permit Number</u>	<u>Subcode</u>	<u>Type</u>	<u>Inspector</u>	<u>Result</u>	<u>Comment</u>	<u>Result Comment</u>
6/16/1999		99157	Plumbing	Final		Pass		ROBERT GAESTEL
6/15/1999		99157	Plumbing	GAS PIPING		Pass		ROBERT GAESTEL

Violations...

There is no violation data for the selected parcel.

Would you like to add an violation to this parcel? [Yes](#)

Ongoing Applications...

There is no application data for the selected parcel.

Would you like to add an application to this parcel? [Yes](#)

▼ Pet...

▼ Complaints...

▼ Land Use...

▼ Engineering...

▼ Code Enforcement...

▼ Health Pro...

- ▼ Fire Prevention...
- ▼ Public Works...
- ▼ Attachments...
- ▼ Comments...