

VIOLATIONS

Premises: Towne Laundromat
309 Bloomfield Avenue
Caldwell, NJ, 07006

Registration No. 7009
Inspection Date: January 24, 2023
Initial Inspector:
Print Name: Robert Spagnuolo
Page number: 1

Owner/Agent: Patrick Aiello

Date:

Inspector:

The violations cited on the above premises are as follows:

Number	Description (Maintenance: 0 Retrofit: 0)	Abate by	U/A	U/A	U/A
1.	Location: Electrical room Nature: Electrical - Clearance around electric panel Code Section: N.J.A.C. 5:70-3,605.3	ABATED			
2.	Location: mechanical room. (water heater, boiler room) Nature: Combustible material shall not be stored in boiler rooms, mechanical rooms, and or electrical rooms. Code Section: N.J.A.C. 5:70-3,315.3.3	ABATED			
3.	Location: Entire premises Nature: Annual fire alarm test records provided to fire official Code Section: N.J.A.C. 5:70-3,901.6.2	ABATED			
4.	Location: behind counter Nature: Alarm systems must be maintained as per NFPA 72. Carbon monoxide detector not working Code Section: N.J.A.C. 5:70-3,901.6.1	ABATED			

Key: The numbering of violations is for identification purposes only and shall not be construed as bearing in any way on the seriousness of any violation.

"U" Unabated - Violation uncorrected.

"A" Abated - Violation corrected.

VIOLATIONS

Premises: Towne Laundromat
309 Bloomfield Avenue
Caldwell, NJ, 07006

Registration No. 7009
Inspection Date: February 24, 2022
Initial Inspector: _____
Print Name: Gary Garamella
Page number: 1

Owner/Agent: Patrick Aiello

Date:

Inspector:

The violations cited on the above premises are as follows:

Number	Description (Maintenance: 0 Retrofit: 0)	Abate by	U/A	U/A	U/A
1.	Location: Laundromat Nature: Emergency lighting must be maintained. Code Section: N.J.A.C. 5:70-3,604.6	ABATED			

Key: The numbering of violations is for identification purposes only and shall not be construed as bearing in any way on the seriousness of any violation.
"U" Unabated - Violation uncorrected.
"A" Abated - Violation corrected.