

Approved

New Jersey Police
Crash Investigation ReportCase No: **18-034792**Page **2** of **3**

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death
E	-	-	-	-			-	-	-	-	-	-	-	
F														
G														
H														
I														
J														

144 Crash Diagram (NOT TO SCALE)



145 Crash Description/Narrative

Vehicle 2 was parked facing east in the driveway of 927 Newark Avenue. Vehicle 1 was backing out of the driveway of 923 Newark Avenue. Vehicle 1 began his turn too soon and backed into Vehicle 2. Vehicle 1 sustained minor damage to the rear passenger side bumper. Vehicle 2 sustained damage to the rear driver side quarter panel and driver side door.

146 Officer's Signature

Christopher Meyler

147 Badge #

0102

148 Reviewer

Robert Surtees


Badge #

0072

149 Case Status

☐ Pending☒ Complete

New Jersey Police Crash Investigation Report Motor Vehicle Crash Diagram	Police Dept: <u>Lacey Police Department</u>	Code: <u>01</u>
	Station: <u>Forked River</u>	Case No: <u>18-034792</u>



Meyler, Christopher

0102