



1. Permits

(All I

<u>Permit Number</u>	<u>Location Address</u>	<u>Owner Name</u>	<u>Application Status</u>	<u>Subcodes Used</u>	
20060194	43 CARPENTER ST	ANDERSON,	Abandoned	E	INSTALL 4 EXTERIOR LIGI
20010115	43 CARPENTER ST	ANDERSON,	CA and Close Date Issued	P	REPLACE SEWER LINE HK
19980015+A	43 CARPENTER STR	J C T BUILDERS	Closed with Date	E	
19980015	43 CARPENTER STR	J C T BUILDERS	CA and Close Date Issued	B P E F	CONSTRUCT INTERIOR N
Grand Totals					

Data, Location Address Like '43 carpenter' ~ 4 records)

Work Description Comments

FTING

DUSE TO CURB

ON BEARING PARTITIONS; NEW SHEETROCK