

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00040827			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 parked properly and unoccupied in parking lot of 525 Jack Martin Blvd. Unknown Vehicle 2 crashes into rear of Vehicle 1 and flees the scene. No surveillance video of the parking lot or witnesses to the crash. No suspect information available for Vehicle 2.

Based on my investigation and observations on scene I determined Vehicle 2 to be at fault for the motor vehicle crash.




146. Officer's Signature William Vendrell	147. Badge # 228	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00040827

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



William Vendrell

Officer's Signature

228

Badge Number