

New Jersey Police Crash Investigation Report												Case Number 2020-00005248			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicles 1 and 2 were in the parking lot of the Wawa convenience store located at 595 Brick Boulevard. Vehicle 1 was backing out of a parking spot from in front of the store. Vehicle 2 was traveling through the lot, and had just pulled behind Vehicle 1 to let off a passenger. The driver of Vehicle 1 stated he did not see Vehicle 2 behind him prior to backing out of the spot. Vehicles 1 and 2 then collided in the traveled portion of the parking lot.

No injuries were reported at the scene. No visible damage to Vehicle 1. Cosmetic damage only to the left rear bumper and tail light of Vehicle 2. No summonses were issued. Both vehicles were driven from the scene.

146. Officer's Signature Christopher Geskey	147. Badge # 184	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report


Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01

Station: — Case No: 2020-00005248

144 Crash Diagram (NOT TO SCALE)

 Indicate North



Christopher Geskey

Officer's Signature

184

Badge Number