


New Jersey Police Crash Investigation Report												Case Number 23-040591		Page <u>2</u> of <u>2</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>	
E	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
F	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
G	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
H	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
I	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
J	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	



145. Crash Description/Narrative

Operator of V1 stated that he was traveling westbound on Brunswick Avenue and had stopped at the stop sign at Valley Road with the intention of making a left turn. He stated that traffic was heavy and that there was a landscaping truck parked on the east side of Valley just north of Brunswick that obstructed his view to the right and other parked cars on the east side of Valley just south of the intersection that obstructed his view to the left. He stated that he believed that he had an opening and began to execute the left turn to travel southbound on Valley. He did not immediately see V1, which was traveling southbound on Valley. V1 collided with V2, causing damage to the passenger's side front fender, tire, and wheel of V1 and the driver's side front bumper, headlight bezel, and headlight of V2. Operator of V2 stated that he was traveling southbound on Valley Road approaching Brunswick Road when V1 executed a left turn directly in his path of travel. Operator of V2 stated that he attempted an evasive maneuver but was unable to avoid the collision. V1 collided with V2, causing the aforementioned damage. All parties involved denied injury on scene.

Lisa Salazzo witnessed the collision. She stated that she was traveling northbound on Valley Road approaching Brunswick when V1 executed a left turn directly in front of her. She stated that she stopped and sounded her horn, but V1 collided with V2.

It should be noted that V2 is a large (Heavy duty) pickup with a large dump bed. It did not have a DOT number or GVW listed on it. Also, V1 was at rest on the west curb of Valley. I am unsure if the tire and wheel damage was from the collision with V2 or from mounting the curb.

146. Officer's Signature Barnes, Christopher 187 Ofcr.		147. Badge # 187	148. Reviewer VRUSSO 225	Badge #	149. Case Status ☐ Pending ☒ Complete
--	--	----------------------------	------------------------------------	---------	---

New Jersey Police Crash Investigation Report	Police Dept. <u>Montclair</u>	Code <u>0 1</u>
Motor Vehicle Crash Description	Station _____	Case No. <u>23-040591</u>

Valley Road

Brunswick Road



V1 At Rest



V1



V2



Not To Scale

