

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E	02	05	01	05	6	F	-	-	-	04			-	ISMARY ARISTEE 214 SUYDAM ST APT 1 NEW BRUNSWICK NJ 08901
F	02	06	01	03	7	F		08	02	04	04		6204	SAILY ARISTEE 214 SUYDAM ST APT 1 NEW BRUNSWICK NJ 08901

144. Crash Diagram



145. Crash Description/Narrative

Investigation revealed that Vehicle 2 was traveling straight ahead through the parking lot of 979 Route 1 when Vehicle 1 entered the roadway after being stopped at the stop sign and struck Vehicle 2. Vehicle 2 had the right of way.

Driver 1 stated she failed to see Vehicle 2 and struck it.
Driver 2 was unable to give a statement at this time due to her injuries.

Driver 2 and Passenger 4 of V2 (Saily) were evaluated on scene by NBTBAS for complaint of pain and were transported to St. Peters Hospital for further evaluation. No other report of injuries. Vehicle's 1 and 2 were both disabled and towed by Puleio's Towing.

Nothing further to report at this time.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Dominguez, Jeffrey	202	Falletta, Christopher	125	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: North Brunswick Police Department Code: 01

Station: - Case No: 23045901

144. Crash Diagram (NOT TO SCALE)

