


NJTR-1 (Rev. 01/22)

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E	02	04	01	05	17	F	-	-	-	04	04	06	-	ANA CLARA LIMA PORTO 337 PINE ST ELIZABETHPORT NJ 07206

144. Crash Diagram



145. Crash Description/Narrative

Driver 1 Stated in Effect: After they pulled up, they stopped suddenly because a car came very fast then I hit them.

Driver 2 Stated in Effect: I was stopped and waiting for traffic to pass so I could go. Then he just hit me.

Investigation Revealed: Vehicle 1 was traveling on Interstate 280 Westbound Exit 6A ramp towards Laurel Avenue in Livingston Township, Essex County. Vehicle 2 was stopped ahead of vehicle 1. Driver 1 was following vehicle 2 too closely and subsequently rear-ended vehicle 2. As a result, vehicle 1 sustained minor damage to the front of the vehicle and vehicle 2 sustained minor damage to the rear of the vehicle. No injuries were reported at the scene.

Other Descriptions

02 - SI #148 ENTERPRISE LEASING CO - SOUTHEAST EAN HOLDINGS LLC - Field 55

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Walker, Michael	8997	McLaughlin, Thomas	5748	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: New Jersey State Police Code: 02

Station: B060 Case No: B060202502108C

144. Crash Diagram (NOT TO SCALE)

