



Construction

Property Summary	Portal Refresh Open All Close All
-------------------------	---

Owner: LU, FAN & HONG, HAIXIA
 Location: 15 MARY COURT
 Block: 4403
 Lot: 5
 Lead Parcel: Yes
 Qualifier:

▼ About the Owner...

▼ About the Property...

▼ About the Taxes...

▼ Projects...

▲ Construction...

Applications... [Shorten](#)

Permit Issue Date	Control Number	Permit Number	Work Type	Subcodes	Status	Close Date	Certificates	Total Cost	Agent
 7/14/2016	C-16-0727	16-0505	Alteration	P	CA and Close Date Issued	8/23/2016	CA	\$1,959	1 800 Heaters
Replace water heater									
 11/25/2014	C-14-0982	14-1087	Alteration	B E	CO and Close Date Issued	1/16/2015	CO	\$36,200	Simply The Best Conservatories & Sunrooms
Exterior Alteration install 16'x12' pre-fab sunroom over existing deck - contractor stated house has existing hardwired smoke detectors									
 9/10/2013	C-13-1047	13-0820	Alteration	B E P F	CA and Close Date Issued	1/8/2014	CA	\$4,201	Durable Molding & Painting Specialists LLC
New Cabinets in existing kitchen using existing plumbing, electric and stove/hood									
 6/19/2013	C-13-0660	13-0522	Alteration	B E	CA and Close Date Issued	8/12/2013	CA	\$8,800	RG Prestige Construction Co LLC
Basement renovation Work done previously WITHOUT Permits, house for sale									
 6/7/2011	C-11-0508	11-0398	Alteration	B	CA and Close Date Issued	6/24/2013	CA	\$7,000	D & D Home Remodelers LLC
Siding address house numbers required - see attached copy									
 5/3/2006	C-06-0440	06-0311	Alteration	B	Closed with Date	5/11/2006		\$7,800	CKG Contracting INC
New roof									
 12/26/2002		02752	Alteration			12/27/2002	CA	\$849	

Would you like to add a application to this parcel? [Yes](#)

Inspections... [Expand](#)

<u>Date</u>	<u>Control Number</u>	<u>Permit Number</u>	<u>Subcode</u>	<u>Type</u>	<u>Inspector</u>	<u>Result</u>	<u>Comment</u>	<u>Result Comment</u>
8/23/2016	C-16-0727	16-0505	Plumbing	WATER HEATER	John Kostrowski	Pass		
8/23/2016	C-16-0727	16-0505	Plumbing	Final	John Kostrowski	Pass		
1/16/2015	C-14-0982	14-1087	Electrical	Final	Joe Marretta	Pass		
1/16/2015	C-14-0982	14-1087	Building	Final	Frank Spallone	Pass		
1/6/2015	C-14-0982	14-1087	Building	INSULATION	Frank Spallone	Pass	under deck floor insulation	
12/22/2014	C-14-0982	14-1087	Electrical	ROUGH	Joe Marretta	Pass	sunroom to inspect how sunroom being attached	
12/3/2014	C-14-0982	14-1087	Building	Progress Insp	Frank Spallone	Pass		
12/1/2014	C-14-0982	14-1087	Building	FRAMING	Frank Spallone	Pass		
12/1/2014	C-14-0982	14-1087	Building	FOOTING	Frank Spallone	Pass		
12/16/2013	C-13-1047	13-0820	Plumbing	Final	John Kostrowski	Pass		

Violations...

There is no violation data for the selected parcel.

Would you like to add an violation to this parcel? [Yes](#)

Ongoing Applications...

There is no application data for the selected parcel.

Would you like to add an application to this parcel? [Yes](#)

- ▼ **Complaints...**
- ▼ **Land Use...**
- ▼ **Engineering...**
- ▼ **Code Enforcement...**
- ▼ **Health Pro...**
- ▼ **Fire Prevention...**
- ▼ **Public Works...**
- ▼ **Attachments...**
- ▼ **Comments...**