



Construction

Property Summary

[Portal](#) | [Refresh](#) | [Open All](#)
| [Close All](#)

Owner: SIBURN, DAVID & JUDITH
 Location: 234 WASHINGTON STREET
 Block: 205
 Lot: 6
 Lead Parcel: Yes
 Qualifier:

▼ About the Owner...

▼ About the Property...

▼ About the Taxes...

▼ Projects...

▲ Construction...

Applications... [Expand](#)

<u>Permit Issue Date</u>	<u>Control Number</u>	<u>Permit Number</u>	<u>Work Type</u>	<u>Subcodes</u>	<u>Status</u>	<u>Close Date</u>	<u>Certificates</u>	<u>Total Cost</u>	<u>Agent</u>
 3/11/2011	C-08-1211	11-0122	Alteration	B	CA and Close Date Issued	3/14/2011	CA	\$5,200	Elwood Builders
Siding									

Would you like to add a application to this parcel? [Yes](#)

Inspections... [Expand](#)

<u>Date</u>	<u>Control Number</u>	<u>Permit Number</u>	<u>Subcode</u>	<u>Type</u>	<u>Inspector</u>	<u>Result</u>	<u>Comment</u>	<u>Result Comment</u>
3/14/2011	C-08-1211	11-0122	Building	Final	Chris Jessen	Pass		

Violations...

There is no violation data for the selected parcel.

Would you like to add an violation to this parcel? [Yes](#)

Ongoing Applications...

There is no application data for the selected parcel.

Would you like to add an application to this parcel? [Yes](#)

▼ Complaints...

▲ Land Use...

Zoning Applications...

There is no application data for the selected parcel.

Board of Adjustment Applications...

There is no application data for the selected parcel.

Planning Board Applications...

There is no application data for the selected parcel.

Historic Board Applications...

There is no application data for the selected parcel.

Zoning Inspections...

There is no zoning inspections data for the selected parcel.

Zoning Violations...

There is no zoning violation data for the selected parcel.

COAH...

There is no COAH data for the selected parcel.

- ▼ Engineering...
- ▼ Code Enforcement...
- ▼ Health Pro...
- ▼ Fire Prevention...
- ▼ Public Works...
- ▼ Attachments...
- ▼ Comments...