


New Jersey Police Crash Investigation Report												Case Number 26-101807		Page <u>2</u> of <u>2</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death	
E	---	---	---	---	---	---	---	---	---	---	---	---	---	-----	
F	---	---	---	---	---	---	---	---	---	---	---	---	---	-----	
G	---	---	---	---	---	---	---	---	---	---	---	---	---	-----	
H	---	---	---	---	---	---	---	---	---	---	---	---	---	-----	
I	---	---	---	---	---	---	---	---	---	---	---	---	---	-----	
J	---	---	---	---	---	---	---	---	---	---	---	---	---	-----	



145. Crash Description/Narrative

Veh-1 was not on scene

Veh-2 stated while they were waiting for the traffic signal veh-1 sideswiped him on the right passenger side and left the scene

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
PO Landaverde, Ismael 561	561	G407		☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report	Police Dept. <u>Union City</u>	Code <u>0 1</u>
Motor Vehicle Crash Description	Station _____	Case No. <u>26-101807</u>

