



Service Ticket No. : ST00637912

Date : 8/8/2025

Frequency : Annual

Service Ticket No. : ST00637912

Inspection Contract No. : 0000050257

PO No. :

Equipment Location :

Fire Alarm Inspection

Property	: Municipal Bldg. (Pre-School Wing)	Owner	: Clark Board Of Education
Address	: 430 Westfield Ave	Address	: 365 Westfield Ave
City	: Clark	City	: Clark
State	: NJ	State	: NJ
Zip	: 07066	Zip	: 07066
Phone	: 7325749600	Phone	: 7325749600

FIRE ALARM INSPECTION SUMMARY

Smoke Detector:	29	Horn / Strobe:	3
Manual Pull Station:	1	Strobe:	12

DEFICIENCIES

None found at time of inspection.

SYSTEM DETAILS

Panel Manufacturer	Silent Knight
Model	5700
Panel Number and/or Location	School Hallway by Room 11
Circuit Class	B
Primary Normal Volts	120
Control Panel Amps	2.5
Over Current Type	Circuit Breaker
Over Current Amps/ MHOs	5.0
Breaker Number	5
Breaker Panel Location	Teen Center
Battery Size	12 Volt 7 Ah
Battery Type	Sealed Lead-Acid
Battery #1 Voltage	12
Battery #1 Amp Hour Rating	7
Battery #2 Voltage	12
Battery #2 Amp Hour Rating	7
Install Date	2021
Last Service Date	08/2025
**Any Panel Defects or Deficiencies?	No

DBA: Metro Fire & Safety • 509 WASHINGTON AVE • CARLSTADT NJ • 07072-2802



Pye-Barker Fire & Safety DBA: Metro Fire & Safety
509 WASHINGTON AVE
CARLSTADT NJ 07072-2802
2016350400
1233PZ@pyebarkerfs.com

Report Cover Page

SERVICE DATE: 8/8/2025

SERVICE TICKET: ST00637912

BUILDING	STREET	CITY	STATE	ZIP
Municipal Bldg. (Pre-School Wing)	430 Westfield Ave	Clark	NJ	07066
BUILDING CONTACT	PHONE			
Customer not on site	7325749600			

System Status: Pass

Please see the attached reports. If there are any questions, please reach out to the above office.

Download your Report at:

<https://customer.pyebarkerfire.com>

Signed 8/8/2025

Inspector: Daniel Toro

Licenses:
NJDFS#P00111

Customer did not sign
Customer not on site
August 8, 2025 12:22 PM
ST00637912 -

Signed 8/8/2025

Building Contact: Customer not on site
Title:

SYSTEM POWER SUPPLY	
Primary Normal Volts	120
Over Current Type	Circuit Breaker

SYSTEM TEST AND INSPECTIONS	
Control Panel (FACP)	
Specify type of inspection	Visual and Functional
Sequence Of Operation	
Specify type of inspection	N/A
Interface Equipment	
Specify type of inspection	N/A
Lamps / Led	
Specify type of inspection	Visual and Functional
Fuses	
Specify type of inspection	N/A
Primary Power Supply	
Specify type of inspection	Visual and Functional
Trouble Signals	
Specify type of inspection	Visual and Functional
Disconnect Switches	
Specify type of inspection	N/A
Ground Fault Monitoring	
Specify type of inspection	N/A
Transient Suppressors	
Specify type of inspection	N/A
Remote Annunciators	
Specify type of inspection	Visual and Functional
Door Holders	
Specify type of inspection	N/A
Heat Detectors	
Were heat detectors tested with heat?	N/A
Does System Have Fixed Temperature, Non-Restorable Link Type or Spot Type Heat Detectors?	No
Have Fixed Temperature, Non-Restorable Link Type or Spot Type Heat Detectors Exceeded The 15 Year Lifespan and Need Replacing?	N/A
**Are There Any Deficiencies To Report?	No

EMERG. COMM. EQUIP / NOTIFICATION APP.

System Performance

Visual	Pass
Functional	Pass

Audible

Visual	Pass
Functional	Pass

Visual

Visual	Pass
Functional	Pass

Speakers

Visual	N/A
Functional	N/A

Phone Set

Visual	N/A
Functional	N/A

Phone Jack

Visual	N/A
Functional	N/A

Off Hook Indicator

Visual	N/A
Functional	N/A

Amplifiers

Visual	N/A
Functional	N/A

Tone Generators

Visual	N/A
Functional	N/A

Call In Signal

Visual	N/A
Functional	N/A

Voice Clarity

Visual	N/A
Functional	N/A

Fireman Phone

Visual	N/A
Functional	N/A

Was dBA meter utilized?

No

**Are There Any Emergency Equipment Deficiencies To Report?

No

MONITORING & NOTIFICATION

On/off Premises Monitoring

Panel Condition Normal On Arrival?	Yes
Time Placed On Test	12:00pm
Monitoring Agency Name	Pride Alarm
Monitoring Agency Phone #	18778449443
Account Number	7220084
Account Password	N/A
Alarm Signal - Received?	Pass
Alarm Restore - Received?	Pass
Trouble Signal - Received?	Pass
Trouble Restored - Received?	Pass
Supervisory Signal - Received?	N/A
Supervisory Restore - Received?	N/A

Notifications Of Testing Completion

Building Management Notified?	Yes
Monitoring Agency Notified?	Yes
Building Occupants Notified?	Yes
Authority Having Jurisdiction Notified?	Yes
Date System Restored to Normal Operation	08/08/2025
Time System Restored to Normal Operation	02:00pm
Fire Alarm Panel Condition Normal On Departure?	Yes
**Inspected and/or Tested Items in This Section Pass or Fail?	Pass

Comments: Clark Police Department
7323883434

DEVICE INSPECTION REPORT

Total Inspected:45

Total Failed:0

Total Passed:45

Device Location	Zone or Address	Type	Make	Model	Sensitivity Range	Sensitivity Alarm Point	Pass / Fail	Comments
Hall By Room 10and Facp		Manual Pull Station		5700			Pass	
Hall By Room 10 And Facp		Horn / Strobe		5700			Pass	
Hall By Room 10 And Facp		Smoke Detector		5700			Pass	
Room 10 Front		Smoke Detector		5700			Pass	

DBA: Metro Fire & Safety • 509 WASHINGTON AVE • CARLSTADT NJ • 07072-2802

Room 10 Front		Strobe		5700			Pass	
Room 10 Rear		Smoke Detector		5700			Pass	
Room 11 By Waiting Room		Smoke Detector		5700			Pass	
Room 11 By Waiting Room		Strobe		5700			Pass	
Room 11 Office		Smoke Detector		5700			Pass	
Room 11 Kitchen		Smoke Detector		5700			Pass	
Room 13 Front		Smoke Detector		5700			Pass	
Room 13		Strobe		5700			Pass	
Room 13 Rear		Smoke Detector		5700			Pass	
Hall By Room 12		Smoke Detector		5700			Pass	
Hall By Room 12		Horn / Strobe		5700			Pass	
Room 12 Front		Smoke Detector		5700			Pass	
Room 12		Strobe		5700			Pass	
Room 12 Rear		Smoke Detector		5700			Pass	
Student Restroom		Smoke Detector		5700			Pass	
Student Restroom		Strobe		5700			Pass	
Hall By Room 14		Smoke Detector		5700			Pass	
Room 14 Front		Smoke Detector		5700			Pass	
Room 14		Strobe		5700			Pass	
Room 14 Rear		Smoke Detector		5700			Pass	
Room 15 Front		Smoke Detector		5700			Pass	
Room 15		Strobe		5700			Pass	
Room 15 Rear		Smoke Detector		5700			Pass	
Hall By Room 16		Smoke Detector		5700			Pass	
Hall By Room 16		Horn / Strobe		5700			Pass	
Storage Electrical Room		Smoke Detector		5700			Pass	
Rear Storage Room		Smoke Detector		5700			Pass	
Tv Control Room		Smoke Detector		5700			Pass	
Tv Control Room		Strobe		5700			Pass	
Room 16 Front		Smoke Detector		5700			Pass	
Room 16		Strobe		5700			Pass	
Room 16 Rear		Smoke Detector		5700			Pass	
Restroom In Room 11		Strobe		5700			Pass	
Tv Studio		Strobe		5700			Pass	
Room 13 Restroom		Smoke Detector		5700			Pass	
Room 13 Restroom		Strobe		5700			Pass	
Room 13 Closet		Smoke Detector		5700			Pass	
Restroom In Room 11		Smoke Detector		5700			Pass	
Tv Studio		Smoke Detector		5700			Pass	
Room 13 Bathroom		Smoke Detector		5700			Pass	
Room 13 Storage		Smoke Detector		5700			Pass	


SIGNATURE

This report was reviewed with: Pye-Barker Fire & Safety

Print Name : Customer not on site

Technician : Daniel Toro

Signature : Customer did not sign
Customer not on site
August 08, 2025 09:14 AM
ST00637912 -

Signature : 

Date : 8/8/2025

Date : 8/8/2025



Pye-Barker Fire & Safety DBA: Metro Fire & Safety
509 WASHINGTON AVE
CARLSTADT NJ 07072-2802
2016350400
1233PZ@pyebarkerfs.com

Report Cover Page

SERVICE DATE: 8/15/2024

SERVICE TICKET: ST00246009

BUILDING	STREET	CITY	STATE	ZIP
Municipal Bldg. (Pre-School Wing)	430 Westfield Ave	Clark	NJ	07066
BUILDING CONTACT	PHONE			
Customer not on site	7325749600			

System Status: Pass

Tag Color: No Tag

Please see the attached reports. If there are any questions, please reach out to the above office.

Download your Report at:

<https://customer.pyebarkerfire.com>

Signed 8/15/2024

Inspector: Daniel Toro

Customer did not sign
Customer not on site
ST00246009

Signed 8/15/2024

Building Contact: Customer not on site
Title:

Licenses:
NJDFS#P00111



Service Ticket No. : ST00246009

Date : 8/15/2024

Frequency : Annual

Service Ticket No. : ST00246009

Inspection Contract No. : 0000050257

PO No. :

Equipment Location :

Fire Alarm Inspection

Property : Municipal Bldg. (Pre-School Wing)
Address : 430 Westfield Ave
City : Clark
State : NJ
Zip : 07066
Phone : 7325749600

Owner : Clark Board Of Education
Address : 365 Westfield Ave
City : Clark
State : NJ
Zip : 07066
Phone : 7325749600

FIRE ALARM INSPECTION SUMMARY

Smoke Detector:	29	Horn / Strobe:	3
Manual Pull Station:	1	Strobe:	12

DEFICIENCIES

None found at time of inspection.

SYSTEM DETAILS

Panel Manufacturer	Silent Knight
Model	5700
Panel Number and/or Location	School Hallway by Room 11
Circuit Class	B
Primary Normal Volts	120
Control Panel Amps	2.5
Over Current Type	Circuit Breaker
Over Current Amps/ MHOs	5.0
Breaker Number	5
Breaker Panel Location	Teen Center
Battery Size	12 Volt 7 Ah
Battery Type	Sealed Lead-Acid
Battery #1 Voltage	12
Battery #1 Amp Hour Rating	7
Install Date	01/01/2021
Battery #2 Voltage	12
Battery #2 Amp Hour	7
Install Date	01/01/2021
Was sensitivity performed during this inspection?	No

DBA: Metro Fire & Safety • 509 WASHINGTON AVE • CARLSTADT NJ • 07072-2802

**Any Panel Defects or Deficiencies?

No

SYSTEM TEST AND INSPECTIONS**Control Panel (FACP)**

Specify type of inspection

Visual and Functional

Sequence Of Operation

Specify type of inspection

Visual & Functional

Interface Equipment

Specify type of inspection

Visual and Functional

Lamps / Led

Specify type of inspection

Visual and Functional

Fuses

Specify type of inspection

Visual

Primary Power Supply

Specify type of inspection

Visual and Functional

Trouble Signals

Specify type of inspection

Visual and Functional

Disconnect Switches

Specify type of inspection

Visual and Functional

Ground Fault Monitoring

Specify type of inspection

Functional

Transient Suppressors

Specify type of inspection

N/A

Remote Annunciators

Specify type of inspection

Visual and Functional

Door Holders

Specify type of inspection

N/A

Heat Detectors

Were heat detectors tested with heat?

N/A

Does System Have Fixed Temperature, Non-Restorable Link Type or Spot Type Heat Detectors?

No

**Have Fixed Temperature, Non-Restorable Link Type or Spot Type Heat Detectors Exceeded The 15 Year Lifespan and Need Replacing?

No

EMERG. COMM. EQUIP / NOTIFICATION APP.**System Performance**

**Visual

Pass

**Functional

Pass

Audible

**Visual

Pass

**Functional

Pass

Visual

**Visual	
**Functional	Pass
Speakers	Pass
**Visual	
**Functional	N/A
Phone Set	N/A
**Visual	
**Functional	N/A
Phone Jack	N/A
**Visual	
**Functional	N/A
Off Hook Indicator	
**Visual	
**Functional	N/A
Amplifiers	N/A
**Visual	
**Functional	N/A
Tone Generators	
**Visual	
**Functional	N/A
Call In Signal	
**Visual	
**Functional	N/A
Voice Clarity	
**Visual	
**Functional	N/A
Fireman Phone	
**Visual	
**Functional	N/A
Was dBA meter utilized?	N/A
	No

MONITORING & NOTIFICATION

On/off Premises Monitoring	
**Panel Condition Normal On Arrival?	Yes
Time Placed On Test	10:15am
Monitoring Agency Name	Pride Alarm
Monitoring Agency Phone #	18778449443
Account Number	7220084
Account Password	N/A
**Alarm Signal - Received?	Pass

**Alarm Restore - Received?	Pass
**Trouble Signal - Received?	Pass
**Trouble Restored - Received?	Pass
**Supervisory Signal - Received?	Pass
**Supervisory Restore - Received?	Pass
Time Verified	11:00am
Verified By	Pride Alarm
Alarm Signal Received 90 Seconds or Less?	Yes
Notifications Of Testing Completion	
Building Management Notified?	Yes
Monitoring Agency Notified?	Yes
Building Occupants Notified?	Yes
Authority Having Jurisdiction Notified?	Yes
**Fire Alarm Panel Condition Normal On Departure?	Yes

DEVICE INSPECTION REPORT

Total Inspected:45

Total Failed:0

Total Passed:45

Device Location	Zone or Address	Type	Make	Model	Sensitivity Range	Sensitivity Alarm Point	Pass / Fail	Comments
Hall By Room 10and Facp		Manual Pull Station		5700			Pass	
Hall By Room 10 And Facp		Horn / Strobe		5700			Pass	
Hall By Room 10 And Facp		Smoke Detector		5700			Pass	
Room 10 Front		Smoke Detector		5700			Pass	
Room 10 Front		Strobe		5700			Pass	
Room 10 Rear		Smoke Detector		5700			Pass	
Room 11 By Waiting Room		Smoke Detector		5700			Pass	
Room 11 By Waiting Room		Strobe		5700			Pass	
Room 11 Office		Smoke Detector		5700			Pass	
Room 11 Kitchen		Smoke Detector		5700			Pass	
Room 13 Front		Smoke Detector		5700			Pass	
Room 13		Strobe		5700			Pass	
Room 13 Rear		Smoke Detector		5700			Pass	
Hall By Room 12		Smoke Detector		5700			Pass	

DBA: Metro Fire & Safety • 509 WASHINGTON AVE • CARLSTADT NJ • 07072-2802

Hall By Room 12		Horn / Strobe		5700			Pass	
Room 12 Front		Smoke Detector		5700			Pass	
Room 12		Strobe		5700			Pass	
Room 12 Rear		Smoke Detector		5700			Pass	
Student Restroom		Smoke Detector		5700			Pass	
Student Restroom		Strobe		5700			Pass	
Hall By Room 14		Smoke Detector		5700			Pass	
Room 14 Front		Smoke Detector		5700			Pass	
Room 14		Strobe		5700			Pass	
Room 14 Rear		Smoke Detector		5700			Pass	
Room 15 Front		Smoke Detector		5700			Pass	
Room 15		Strobe		5700			Pass	
Room 15 Rear		Smoke Detector		5700			Pass	
Hall By Room 16		Smoke Detector		5700			Pass	
Hall By Room 16		Horn / Strobe		5700			Pass	
Storage Electrical Room		Smoke Detector		5700			Pass	
Rear Storage Room		Smoke Detector		5700			Pass	
Tv Control Room		Smoke Detector		5700			Pass	
Tv Control Room		Strobe		5700			Pass	
Room 16 Front		Smoke Detector		5700			Pass	
Room 16		Strobe		5700			Pass	
Room 16 Rear		Smoke Detector		5700			Pass	
Restroom In Room 11		Strobe		5700			Pass	
Tv Studio		Strobe		5700			Pass	
Room 13 Restroom		Smoke Detector		5700			Pass	
Room 13 Restroom		Strobe		5700			Pass	
Room 13 Closet		Smoke Detector		5700			Pass	
Restroom In Room 11		Smoke Detector		5700			Pass	
Tv Studio		Smoke Detector		5700			Pass	
Room 13 Bathroom		Smoke Detector		5700			Pass	
Room 13 Storage		Smoke Detector		5700			Pass	

SIGNATURE

This report was reviewed with:

Pye-Barker Fire & Safety

Print Name : Customer not on site

Technician : Daniel Toro


DBA: Metro Fire & Safety • 509 WASHINGTON AVE • CARLSTADT NJ • 07072-2802

Service Ticket No. : ST00246009

Signature

Customer did not sign
Customer not on site
August 15, 2024 12:15 PM
ST00246009 -

Signature



Date

: 8/15/2024

Date

: 8/15/2024

Report of Inspection / Test

Annual NFPA 72-13

2023-08-10

Property

Municipal Bldg. (Pre-school wing)

430 Westfield Avenue

Clark NJ 7066

Damian 9086237369

Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety

P00111

509 Washington Ave

Carlstadt NJ 07072

201-635-0400

reports@metrofire.com



Inspection and Testing Form - Fire Alarm - Pass

Devices	Tested this Inspection	Pass	Fail	Tested YTD	Not Tested YTD	Total
Horn Strobe	3	3	0	3	0	3
Strobe	12	12	0	12	0	12
Smoke Detector	27	27	0	27	0	27
Pull Station	1	1	0	1	0	1

Report of Inspection / Test

Annual NFPA 72-13



2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com

Monitoring Entity

Contact Name	Ultimate Security	Telephone	973-535-0515
Reference Number	722-0084	Type Transmission	Phone

Approving Agency

Contact Name	Fire Department	Telephone	732-388-3434
Email	N/A	Service Type	N/A

System Type

Control Unit Manufacturer	Silent Knight.	Model Number	5700
Circuit Styles	SLC	Software Revision	N/A
Date Last Serviced	2023-08-09	Last Date and Software or Configuration was Revised	N/A
Number of Circuits	1		

Power Supply

Main Nominal Voltage	120	Main Nominal Amps	20
Overcurrent Protection	Circuit Breaker	Panel Board Location	Teen Center Panel B
Disconnecting Means Location	CB 5	Secondary Standby	2x12vdc
Storage Battery: Amp Hour Rating	7 ah	Calculated Capacity to operate system (Hours)	N/A
Engine-driven generator dedicated to fire alarm system	N/A	Location of fuel storage	N/A
Has Emergency System described in NFPA 70, Article 700	N/A	Has Legally required standby described in NFPA 70, Article 701	N/A
Has Optional standby system described in NFPA 70, Article 702, which also meets the performance requirements of Article 700 or 701	N/A		

Report of Inspection / Test

Annual NFPA 72-13

2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com



NOTIFICATIONS MADE PRIOR TO ANY TESTING		Yes	No	N/A	Who	Time
Monitoring Entity		☒	☐	☐	Ultimate Security	
Building Occupants		☒	☐	☐		
Building Management		☒	☐	☐		
Other (Specify)		☒	☐	☐	Clark PD	
AHJ Notified of Any Impairments		☐	☐	☒		

SYSTEM TESTS AND INSPECTIONS	Visual	Functional	Pass/Fail	Comments
Control Unit	Yes	Yes	Pass	
Interface Equipment	N/A	N/A	N/A	
Lamps/LEDS	Yes	Yes	Pass	
Fuses	N/A	N/A	N/A	
Primary Power Supply	Yes	Yes	Pass	
Trouble Signals	Yes	Yes	Pass	
Disconnect Switches	N/A	N/A	N/A	
Ground-Fault Monitoring	N/A	N/A	N/A	
Supervision	N/A	N/A	N/A	
Local Annunciator	Yes	Yes	Pass	
Remote Annunciator	Yes	Yes	Pass	
Power Extender Panels	N/A	N/A	N/A	
Isolation Modules	N/A	N/A	N/A	
Sound Pressure Level- Ambient	N/A	N/A	N/A	
Sound Pressure Level- Alarm	N/A	N/A	N/A	
System Intelligibility - CSI	N/A	N/A	N/A	
System Intelligibility - STI	N/A	N/A	N/A	
Functional Test	Yes	Yes	Pass	
Reset/Power down Test	Yes	Yes	Pass	
UPS Power Test	N/A	N/A	N/A	
CCU Security Mechanism	N/A	N/A	N/A	
Prerecorded Message Content	N/A	N/A	N/A	

Report of Inspection / Test

Annual NFPA 72-13



2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com

Prerecorded Message Activation	N/A	N/A	N/A	
Software Backup Performed	N/A	N/A	N/A	
Test Backup Software	N/A	N/A	N/A	
Fire Alarm to MNS Interface	N/A	N/A	N/A	
MNS to Fire Alarm Interface	N/A	N/A	N/A	
In-building MNS to wide area MNS	N/A	N/A	N/A	
MNS to direct recipient MNS	N/A	N/A	N/A	
Other (Specify)	N/A	N/A	N/A	
SECONDARY POWER	Visual	Functional	Pass/Fail	Comments
Battery Condition	Yes	Yes	Pass	
Load Voltage	Yes	Yes	Pass	
Discharge Test	N/A	N/A	N/A	
Charger Test	N/A	N/A	N/A	
Transient Suppressors	N/A	N/A	N/A	
Remote Annunciators	N/A	N/A	N/A	
NOTIFICATION APPLIANCES	Visual	Functional	Pass/Fail	Comments
Audible	Yes	Yes	Pass	
Visual	Yes	Yes	Pass	
Speakers	N/A	N/A	N/A	
Voice Clarity	N/A	N/A	N/A	
EMERGENCY COMMUNICATION EQUIPMENT	Visual	Functional	Pass/Fail	Comments
Phone Set	N/A	N/A	N/A	
Phone Jacks	N/A	N/A	N/A	
Off-Hook Indicator	N/A	N/A	N/A	
Amplifier(s)	N/A	N/A	N/A	
Tone Generator(s)	N/A	N/A	N/A	
Call-in Signal	N/A	N/A	N/A	
System Performance	N/A	N/A	N/A	

Report of Inspection / Test

Annual NFPA 72-13

2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com



System Audibility	N/A	N/A	N/A		
System Intelligibility	N/A	N/A	N/A		
Elevator Emergency Communication System	N/A	N/A	N/A		
Other (Specify)	N/A	N/A	N/A		
AUXILIARY FUNCTIONS/INTERFACE EQUIPMENT/SPECIAL HAZARDS	Visual	Functional	Pass/Fail	Comments	
Door-Releasing Devices	N/A	N/A	N/A		
Fan Shutdown	N/A	N/A	N/A		
Door Unlocking	N/A	N/A	N/A		
Elevator Recall	N/A	N/A	N/A		
Elevator Shunt-Trip	N/A	N/A	N/A		
MNS Override of FA signals	N/A	N/A	N/A		
Other (Specify)	N/A	N/A	N/A		
SUPERVISING STATION MONITORING	Yes	No	N/A	Who	Time
Alarm Signal	☒	☐	☐	Ultimate Security	
Alarm Restoration	☒	☐	☐	Ultimate Security	
Supervisory Signal	☒	☐	☐	Ultimate Security	
Supervisory Restoration	☒	☐	☐	Ultimate Security	
Trouble Signals	☒	☐	☐	Ultimate Security	
Trouble Restoral	☒	☐	☐	Ultimate Security	
NOTIFICATIONS THAT TESTING IS COMPLETE	Yes	No	N/A	Who	Time
Monitoring Agency	☒	☐	☐	Ultimate Security	
Building Occupants	☒	☐	☐		
Building Management	☒	☐	☐		
AHJ Notified of Any Impairments	☐	☐	☒		
Other (Specify)	☒	☐	☐	Clark PD	

Report of Inspection / Test

Annual NFPA 72-13



2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com

INITIATING, SUPERVISORY, AND NOTIFICATION DEVICE TESTS AND INSPECTIONS

Address	Location	Device Type	Factory Setting	Measured Setting	Visual	Functional	Pass/Fail
	Hall by Room 10 and FACP	Pull Station			Yes	Yes	Pass (2023-08-09)
	Hall by Room 10 and FACP	Horn Strobe			Yes	Yes	Pass (2023-08-09)
	Hall by Room 10 and FACP	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 10 Front	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 10 Front	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 10 Rear	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 11 by Waiting Room	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 11 by Waiting Room	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 11 Office	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 11 Kitchen	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 13 Front	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 13	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 13 Rear	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Hall by Room 12	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Hall by Room 12	Horn Strobe			Yes	Yes	Pass (2023-08-09)
	Room 12 Front	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 12	Strobe			Yes	Yes	Pass (2023-08-09)

Report of Inspection / Test

Annual NFPA 72-13

2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com



Address	Location	Device Type	Factory Setting	Measured Setting	Visual	Functional	Pass/Fail
	Room 12 Rear	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Student Restroom	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Student Restroom	Strobe			Yes	Yes	Pass (2023-08-09)
	Hall by Room 14	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 14 Front	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 14	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 14 Rear	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 15 Front	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 15	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 15 Rear	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Hall by Room 16	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Hall by Room 16	Horn Strobe			Yes	Yes	Pass (2023-08-09)
	Storage Electrical Room	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Rear Storage Room	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	TV Control Room	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	TV Control Room	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 16 Front	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 16	Strobe			Yes	Yes	Pass (2023-08-09)

Report of Inspection / Test

Annual NFPA 72-13



2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com

Address	Location	Device Type	Factory Setting	Measured Setting	Visual	Functional	Pass/Fail
	Room 16 Rear	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Restroom in Room 11	Strobe			Yes	Yes	Pass (2023-08-09)
	TV Studio	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 13 Restroom	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Room 13 Restroom	Strobe			Yes	Yes	Pass (2023-08-09)
	Room 13 Closet	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	Restroom in Room 11	Smoke Detector			Yes	Yes	Pass (2023-08-09)
	TV Studio	Smoke Detector			Yes	Yes	Pass (2023-08-09)

Report of Inspection / Test

Annual NFPA 72-13

2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com



Control Panel and Battery Readings

Location: End of Hall by Room 10				
Manufacturer: Silent Knight				
Model: 5700				
AC Power Supply Volts AC	DC Power Supply Volts DC	Load Test %	Battery w/Charger	Battery w/Out Charger
Battery Date	AC Loss Causes Trouble	DC Loss Causes Trouble	Battery Voltage & AH Rating	Ground Fault
Battery Voltage AH Rating	Battery Voltage AH Rating w/Charger	Battery Voltage AH Rating w/Out Charger	Battery Voltage & AH Rating Under Load	
Comments				

Report of Inspection / Test

Annual NFPA 72-13



2023-08-10

Property

Municipal Bldg. (Pre-school wing)
430 Westfield Avenue
Clark NJ 7066
Damian 9086237369
Print Date: 2023-08-10

Conducted by: Alarm_2

Metro Fire & Safety
P00111
509 Washington Ave
Carlstadt NJ 07072
201-635-0400
reports@metrofire.com

Deficiencies - Fire Alarm

None