



517 GREEN GROVE ROAD
PO BOX 607
NEPTUNE, NEW JERSEY 07754
P: 732.922.3399 | F: 732.918.8668
ALLIEDFIRESAFETY.COM



Work Order #144045

Service Location		AR Customer	
Service Location:	Borough of Mantoloking	Customer:	MANBOR - Borough of Mantoloking
Address:	202 Downer Avenue	Address	340 Drum Point Road, 2nd Floor
City, State, Zip:	Mantoloking NJ 087380247	City, State, Zip	Brick NJ 08723
Contact:	Scott Hulse	Main Phone:	(732)899-9643
Contact Phone:	(732)899-6600	Payment Terms:	Terms

Work Order Details	
Call Type:	PM's
Problem Type:	E-Extinguisher Inspection Needed
Job Status:	Completed
Date Scheduled:	7/2/2021
WO # / FCO #:	144045
Alt WO#:	
Customer PO #:	
Technician:	Bollettino;Robert

Description of Service
Annual Extinguisher Insp

Work Order Comments
Date: 6/21/2021, Entered By: Bollettino;Robert, Subject: Form Attachment
Date: 6/21/2021, Entered By: Bollettino;Robert, Subject: Fire Extinguisher Inspection
Fire Extinguisher Inspection Completed as per NFPA 10 and the State of New Jersey Uniform Fire Code.

Work Order Items		
Date	Description	Qty
6/21/2021	E - Fire Extinguisher Service Call	1.00
6/21/2021	E - Fire Extinguisher Inspection	25.00
6/21/2021	E - 2.5 Gal Water Recharge	1.00
6/21/2021	E - 10# ABC Dry Chem Recharge	1.00
6/21/2021	E - 10# ABC Dry Chem 6 Year Tear Down	5.00
6/21/2021	E - 10# ABC Dry Chem Hydro/Recharge	5.00
6/21/2021	E - 6LWet Chem Hydro/Recharge	2.00
6/21/2021	E - 10# CO2 Hydro/Recharge	1.00
6/21/2021	E - CO2 Continuity Test	4.00
6/23/2021	E - Dry Chem O-Ring	11.00
6/23/2021	E - Dry Chem Valve Stem	11.00
6/23/2021	E - Dry Chem Valve Rebuilt	11.00
6/23/2021	E - CO2 O-Ring	1.00
6/23/2021	E - Hose Strap	1.00

Parts Items		
Date	Description	Qty

By signing I agree to the information and description of services as explained above as well as the General Terms and Conditions that are available on our website at <https://www.alliedfiresafety.com/Site/ServiceTerms>. A hard copy will be furnished upon request.

Customer Signature					
Signature		Signed By	SH	Date	7/2/2021

NJ FIRE PERMIT # P00166 - DOT REGISTRATION # A010 - NJ ELECTRICAL LICENSE # 11327 - NJ CERTIFIED SBE



517 GREEN GROVE ROAD
PO BOX 607
NEPTUNE, NEW JERSEY 07754
P: 732.922.3399 | F: 732.918.8668
ALLIEDFIRESAFETY.COM



Fire Extinguisher Inspection

Tech:	Bolletino;Robert	Customer Id:	MANBOR
Service Site:	Borough of Mantoloking		
Address:	202 Downer Avenue Mantoloking, NJ 087380247		
Date:	6/21/2021	Work Order:	144045

FIRE EXTINGUISHER LOCATION SHEET										
TYPE	MFG	MFG YEAR	LOCATION	SERVICE					ADDITIONAL / NOTES	
Select Number of Extinguishers >>										40
5# ABC	Kidde	2017	PD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
5# ABC	Kidde	2017	PD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2018	PD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2018	PD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2015	PD	☐ Inspection	☐ Recharge	☒ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
5# CO2	Amerex	2001	PD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2007	PD	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Condemned	☐ New	
10# CO2	Kidde	1979	DPW	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
2½# ABC	Badger	1999	DPW	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
5# ABC	Kidde	2006	DPW	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Badger	2008	DPW	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Condemned	☐ New	
10# ABC	Badger	2008	DPW	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Condemned	☐ New	
5# ABC	Kidde	2004	DPW	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
15# CO2	Kidde	2005	DPW	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	1990	DPW	☐ Inspection	☐ Recharge	☒ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2000	DPW	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
2½ Gal Water	Ansul	2010	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
20# ABC	Amerex	2010	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# CO2	Badger	2005	FD	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Condemned	☐ New	
6L Wet Chemical	Amerex	2016	FD	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Condemned	☐ New	
5# CO2	Amerex	2007	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
2½ Gal Water	Amerex	2015	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
5# BC	Amerex	2006	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
6L Wet Chemical	Amerex	1996	FD	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Condemned	☐ New	
10# CO2	Kidde	1979	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
20# ABC	Kidde	1994	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
20# ABC	Buckeye	1995	FD	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2018	DPW	☐ Inspection	☒ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2015	Town Hall	☐ Inspection	☐ Recharge	☒ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2015	Town Hall	☐ Inspection	☐ Recharge	☒ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	1990	Town Hall	☐ Inspection	☐ Recharge	☒ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2018	Town Hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	
10# ABC	Amerex	2018	Town Hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Condemned	☐ New	

10# ABC

Amerex

2018

Town Hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Condemned

☐ New

10# ABC

Amerex

2018

Town Hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Condemned

☐ New

10# ABC

Amerex

2018

Town Hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Condemned

☐ New

10# ABC

Amerex

2019

Town Hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Condemned

☐ New

2½ Gal Water

Amerex

1995

FD

☐ Inspection

☒ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Condemned

☐ New

10# ABC

Amerex

1990

FD

☐ Inspection

☐ Recharge

☐ 6 Year Maint.

☒ Hydrotest

☐ Condemned

☐ New

10# ABC

Amerex

2005

FD

☐ Inspection

☐ Recharge

☐ 6 Year Maint.

☒ Hydrotest

☐ Condemned

☐ New

FIRE EXTINGUISHER SERVICE SUMMARY																			
	2½ Gal PW	2½# ABC	5# ABC	6# ABC	10# ABC	20# ABC	6L WC	5# CO2	10# CO2	15# CO2	20# CO2	5# Halotron	11# Halotron	5# BC	6# BC	10# BC	20# BC	Other	Totals
Inspection	2	1	4	0	9	3	0	2	2	1	0	0	0	1	0	0	0	0	25
Recharge	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
6-Year Maint.	0	0	0	0	5	0	0	0	0	0	0	0	0	0	0	0	0	0	5
Hydrotest	0	0	0	0	5	0	2	0	1	0	0	0	0	0	0	0	0	0	8
New	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Condemned	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CO2																			
Conductivity									3	1	0								4

ACKNOWLEDGEMENT

On this date, the extinguishers at the above location were tested and inspected in accordance with procedures of the most recent adopted editions of NFPA 10 and State of New Jersey Uniform Fire Code and was operated according to these procedures with the results indicated above. Any comments or unsatisfactory marks have been explained to the customer/customer's agent below. AS PER LAW, A COPY OF THIS REPORT WILL BE FORWARDED TO THE AUTHORITY HAVING JURISDICTION (I.E. FIRE MARHSAL).

Customer Name: Scott Hulse

Customer Signature:



INSPECTOR'S INFORMATION

I state that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operating condition upon completion of this inspection except as noted above.

Inspector Name: RB

Inspector Signature:



Date: 6/21/21