



517 GREEN GROVE ROAD
PO BOX 607
NEPTUNE, NEW JERSEY 07754
P: 732.922.3399 | F: 732.918.8668
ALLIEDFIRESAFETY.COM



Work Order #167452

Service Location		AR Customer	
Service Location:	Borough of Mantoloking	Customer:	MANBOR - Borough of Mantoloking
Address:	202 Downer Avenue	Address	340 Drum Point Road, 2nd Floor
City, State, Zip:	Mantoloking NJ 087380247	City, State, Zip	Brick NJ 08723
Contact:	Scott Hulse	Main Phone:	(732)899-9643
Contact Phone:	(732)899-6600	Payment Terms:	Terms

Work Order Details	
Call Type:	PM's
Problem Type:	E-Extinguisher Inspection Needed
Job Status:	Completed
Date Scheduled:	6/22/2023
WO # / FCO #:	167452
Alt WO#:	
Customer PO #:	
Technician:	Fascia;Alan

Description of Service
Annual Fire Extinguisher Insp - CALL SCOTT UPON ARRIVAL 917 455 4005

Work Order Comments
Date: 6/14/2023, Entered By: Fascia;Alan, Subject: Fire Extinguisher Inspection (w/ Replaced Extingui
Fire Extinguisher Inspection Completed as per NFPA 10 and the State of New Jersey Uniform Fire Code. Condemned Fire Extinguisher(s) Replaced with New.
Date: 6/22/2023, Entered By: Fascia;Alan, Subject: Form Attachment

Work Order Items		
Date	Description	Qty
6/14/2023	E - Fire Extinguisher Service Call	1.00
6/14/2023	E - Fire Extinguisher Inspection	34.00
6/14/2023	E - CO2 Continuity Test	4.00
6/15/2023	E - 2.5 Gal Water Recharge	1.00
6/15/2023	E - 5# ABC Dry Chem 6 Year Tear Down	1.00
6/15/2023	E - 20# ABC Dry Chem Hydro/Recharge	1.00
6/15/2023	E - 5# CO2 Hydro/Recharge	1.00
6/15/2023	E - 15# CO2 Hydro/Recharge	1.00
6/16/2023	E - Water Valve Rebuild Kit	1.00
6/16/2023	E - Dry Chem Valve Rebuild Kit	2.00
6/16/2023	E - CO2 O-Ring	2.00

Parts Items		
Date	Description	Qty
6/14/2023	10914 Buckeye 5lb ABC FE	2.00
6/14/2023	16888 Badger 2.5 Gallon Water Extinguisher	2.00
6/14/2023	45600 Buckeye 10lb CO2 FE	1.00

By signing I agree to the information and description of services as explained above as well as the General Terms and Conditions that are available on our website at <https://www.alliedfiresafety.com/Site/ServiceTerms>. A hard copy will be furnished upon request.

Customer Signature					
Signature			Signed By	NTS	Date 6/22/2023

NJ FIRE PERMIT # P00166 - DOT REGISTRATION # A010 - NJ ELECTRICAL LICENSE # 11327 - NJ CERTIFIED SBE



517 GREEN GROVE ROAD
PO BOX 607
NEPTUNE, NEW JERSEY 07754
P: 732.922.3399 | F: 732.918.8668
ALLIEDFIRESAFETY.COM



Fire Extinguisher Inspection

Tech:	Fascia;Alan	Customer Id:	MANBOR
Service Site:	Borough of Mantoloking		
Address:	202 Downer Avenue Mantoloking, NJ 087380247		
Date:	6/14/2023	Work Order:	167452

FIRE EXTINGUISHER LOCATION SHEET												
TYPE	MFG	MFGYEAR	LOCATION	SERVICE					ADDITIONAL / NOTES			
Select Number of Extinguishers >> 43												
10# ABC	Amerex	1990	Public works	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2027		
5# ABC	Kidde	1996	Public works	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2024		
5# CO2	Amerex	2001	Public works	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2027		
10# CO2	Strike First	2023	Public works	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☒ Non-Compliant	☒ New	Not UL711 H2028		
15# CO2	Kidde	1995	Public works	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2025		
5# CO2	Amerex	2010	Public works	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Non-Compliant	☐ New	H2028		
5# BC	Amerex	2006	Public works	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2026		
5# ABC	Kidde	2017	Public works	☐ Inspection	☐ Recharge	☒ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2029		
5# ABC	Badger	1999	Public works	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2025		
10# ABC	Amerex	2000	Public works	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2026		
2½ Gal Water	Senty	2010	Firehouse	☐ Inspection	☒ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2025		
5# ABC	Kidde	2013	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2028		
Other	Buckeye	2007	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2028		
5# ABC	Kidde	2004	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2026		
2½ Gal Water	Amerex	1995	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2026		
15# CO2	Badger	2010	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2026		
10# ABC	Amerex	1990	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2027		
20# ABC	Kidde	1995	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2026		
20# ABC	Amerex	2010	Firehouse	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☒ Hydrotest	☐ Non-Compliant	☐ New	6yr2029		
5# ABC	Buckeye	2023	Firehouse	☐ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☒ Non-Compliant	☒ New	Rust/6yr2029		
2½ Gal Water	Amerex	2015	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2025		
5# CO2	Amerex	2007	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2027		
20# ABC	Buckeye	1996	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2026		
10# ABC	Amerex	2018	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2028		
6L Wet Chemical	Amerex	2016	Firehouse	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2026		
10# ABC	Amerex	2005	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2027		
10# ABC	Amerex	2018	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2024		
10# ABC	Amerex	2018	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2024		
10# ABC	Badger	2008	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2027		
10# ABC	Amerex	2015	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2027		
10# ABC	Amerex	2018	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2024		
10# ABC	Amerex	2018	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	6yr2024		
10# ABC	Amerex	1990	Boro hall	☒ Inspection	☐ Recharge	☐ 6 Year Maint.	☐ Hydrotest	☐ Non-Compliant	☐ New	H2027		

10# ABC

Amerex

2015

Boro hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☐ New

H2027

10# ABC

Amerex

2014

Boro hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☐ New

H2026

10# ABC

Amerex

2018

Boro hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☐ New

6yr2024

10# ABC

Amerex

2018

Boro hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☐ New

6yr2024

10# ABC

Amerex

2018

Boro hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☐ New

6yr2024

10# ABC

Amerex

2019

Boro hall

☒ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☐ New

6yr2025

2½ Gal Water

Badger

2023

Firehouse

☐ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☒ New

H2028

2½ Gal Water

Badger

2023

Firehouse

☐ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☐ Non-Compliant

☒ New

H2028

15# CO2

Kidde

1993

Firehouse

☐ Inspection

☐ Recharge

☐ 6 Year Maint.

☒ Hydrotest

☐ Non-Compliant

☐ New

H2028

5# ABC

Buckeye

2023

Firehouse

☐ Inspection

☐ Recharge

☐ 6 Year Maint.

☐ Hydrotest

☒ Non-Compliant

☒ New

6yr2029

FIRE EXTINGUISHER SERVICE SUMMARY																				
	2½ Gal PW	2½# ABC	5# ABC	6# ABC	10# ABC	20# ABC	6L WC	5# CO2	10# CO2	15# CO2	20# CO2	5# Halotron	11# Halotron	5# BC	6# BC	10# BC	20# BC	Other	Totals	
Inspection	2	0	4	0	18	2	1	2	0	2	0	0	0	1	0	0	0	2	34	
Recharge	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
6-Year Maint.	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Hydrotest	0	0	0	0	0	1	0	1	0	1	0	0	0	0	0	0	0	0	3	
New	2	0	2	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	5	
Non-Compliant	0	0	2	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	3	
CO2 Conductivity									2	3	0									5

ACKNOWLEDGEMENT

On this date, the extinguishers at the above location were tested and inspected in accordance with procedures of the most recent adopted editions of NFPA 10 and State of New Jersey Uniform Fire Code and was operated according to these procedures with the results indicated above. Any comments or unsatisfactory marks have been explained to the customer/customer's agent below. AS PER LAW, A COPY OF THIS REPORT WILL BE FORWARDED TO THE AUTHORITY HAVING JURISDICTION (I.E. FIRE MARHSAL).

Customer Name: NTS

Customer Signature:

INSPECTOR'S INFORMATION

I state that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operating condition upon completion of this inspection except as noted above.

Inspector Name: Alan Fascia

Inspector Signature:



Date: 6/14/23