


NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death	

144. Crash Diagram



145. Crash Description/Narrative

Vehicle 1 was observed on Ring doorbell footage, pulling out of the 8th street bistro parking lot. While doing so, the driver struck the back left bumper of vehicle 2. Vehicle 1 then left the scene shortly after.

Owner of Vehicle 2 stated he came outside of his apartment and observed the left side of his back bumper scratched.

*It should be noted there was a ring doorbell camera (owned by Manual Enamorado Jr [REDACTED]) outside the front of 7 Linnet Street that captured the incident.

Other Descriptions

01 - 00 - Field 25

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
HOJNACKI, JOSEPH	0065	LOBUE, JOHN	0099	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Bayonne Police Department Code: 01

Station: Bayonne Case No: 2025-36952

144. Crash Diagram (NOT TO SCALE)

