




STATE OF NEW JERSEY
MOTOR VEHICLE COMMISSION



School Bus Inspection Reporting System

Company Name: LACEY TOWNSHIP BOARD OF EDUCATION

Address: 200 WESTERN BOULEVARD

City: LANOKA HARBOR

County: Ocean

Zip Code: 08734

School Bus Company Statistical Summary:

Initial Out of Service Failure Rate: 12%

Initial Inspection Passing Rate: 87%

Number of School Bus Inspection Report(s) Found: 58

Note: Click View to select the inspection report for the report card details.

Out of Service Rejections:

Details	License No.	Bus No.	Inspection Date	Initial Approval	Reexam Approval	Approval No.

View	H189S1	S2	2023-08-22	N	Y	20242418328
View	M817S1	S7	2023-08-22	N	Y	20242418332
View	V880S1	4	2023-08-23	N	Y	20242418344
View	A617S1	48	2023-08-23	N	Y	20242418345
View	Y982S1	15	2023-08-25	N	Y	20242418361
View	Y983S1	16	2023-08-25	N	Y	20242418363

« « « « « « « » » » » » » » » » »

30 Day Defect(s):

[illegible]

View	A111S1	S3	2023-08-25	N	Pending for Reexam
------	--------	----	------------	---	--------------------

«««« «« « » »» »»»»»»

Initial Approvals:

[illegible]

View	C106S1	24L	2023-08-21	Y	20242418318
View	J132S1	22L	2023-08-21	Y	20242418317
View	E605S1	50	2023-08-21	Y	20242418319
View	S1R346	9	2023-08-21	Y	20242418320
View	R559S1	8	2023-08-21	Y	20242418321
View	C104S1	23	2023-08-21	Y	20242418323
View	S1X648	27I	2023-08-21	Y	20242418322
View	T230S1	20	2023-08-22	Y	20242418324

«««« «« «12345» »» »»»»»

Details License No. Bus No. Inspection Date Initial Approval Reexam Approval Approval No.

View	T229S1	18	2023-08-22	Y		20242418326
View	V885S1	2	2023-08-22	Y		20242418325

«««« «« «12345» »» »»»»

[Back](#)



STATE OF NEW JERSEY
MOTOR VEHICLE COMMISSION



School Bus Inspection Reporting System

Company Name: LACEY TOWNSHIP BOARD OF EDUCATION

Address: 200 WESTERN BOULEVARD

City: LANOKA HARBOR

County: Ocean

Zip Code: 08734

School Bus Company Statistical Summary:

Initial Out of Service Failure Rate: 12%

Initial Inspection Passing Rate: 87%

Number of School Bus Inspection Report(s) Found: 58

Note: Click View to select the inspection report for the report card details.

Out of Service Rejections:

[illegible]

View	H189S1	S2	2023-08-22	N	Y	20242418328
View	M817S1	S7	2023-08-22	N	Y	20242418332
View	V880S1	4	2023-08-23	N	Y	20242418344
View	A617S1	48	2023-08-23	N	Y	20242418345
View	Y982S1	15	2023-08-25	N	Y	20242418361
View	Y983S1	16	2023-08-25	N	Y	20242418363

<<<< << < > >> >>>>

30 Day Defect(s):

[illegible]

View	A111S1	S3	2023-08-25	N	Pending for Reexam
------	--------	----	------------	---	--------------------

««««« ««« « » »» »»»»»»

Initial Approvals:

	Details	License No.	Bus No.	Inspection Date	Initial Approval	Reexam Approval	Approval No.
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							
51							
52							
53							
54							
55							
56							
57							
58							
59							
60							
61							
62							
63							
64							
65							
66							
67							
68							
69							
70							
71							
72							
73							
74							
75							
76							
77							
78							
79							
80							
81							
82							
83							
84							
85							
86							
87							
88							
89							
90							
91							
92							
93							
94							
95							
96							
97							
98							
99							

View	G230S1	S19	2023-08-22	Y	20242418327
View	J310S1	S5	2023-08-22	Y	20242418329
View	U338S1	S4	2023-08-22	Y	20242418330
View	R228S1	35	2023-08-22	Y	20242418331
View	F333S1	8L	2023-08-22	Y	20242418333
View	K592S1	25	2023-08-22	Y	20242418334
View	S1Y355	13	2023-08-23	Y	20242418335
View	S1Y354	11	2023-08-23	Y	20242418336

«««« «« «12345» »» »»»»

Details License No. Bus No. Inspection Date Initial Approval Reexam Approval Approval No.


View	S1X650	7	2023-08-23	Y		20242418337
View	F334S1	9	2023-08-23	Y		20242418338

«««« «« «12345»»»»»»»»»»

Back



STATE OF NEW JERSEY
MOTOR VEHICLE COMMISSION



School Bus Inspection Reporting System

Company Name: LACEY TOWNSHIP BOARD OF EDUCATION

Address: 200 WESTERN BOULEVARD

City: LANOKA HARBOR

County: Ocean

Zip Code: 08734

School Bus Company Statistical Summary:

Initial Out of Service Failure Rate: 12%

Initial Inspection Passing Rate: 87%

Number of School Bus Inspection Report(s) Found: 58

Note: Click View to select the inspection report for the report card details.

Out of Service Rejections:

Details	License No.	Bus No.	Inspection Date	Initial Approval	Reexam Approval	Approval No.

View	H189S1	S2	2023-08-22	N	Y	20242418328
View	M817S1	S7	2023-08-22	N	Y	20242418332
View	V880S1	4	2023-08-23	N	Y	20242418344
View	A617S1	48	2023-08-23	N	Y	20242418345
View	Y982S1	15	2023-08-25	N	Y	20242418361
View	Y983S1	16	2023-08-25	N	Y	20242418363

«««« «« «» »»» »»»»»»

30 Day Defect(s):

[illegible]

View	A111S1	S3	2023-08-25	N	Pending for Reexam
----------------------	--------	----	------------	---	--------------------

«««« «« « » »» »»»»»

Initial Approvals:

[illegible]

View	F335S1	10	2023-08-23	Y	20242418339
View	E313S1	52	2023-08-23	Y	20242418340
View	C105S1	12	2023-08-23	Y	20242418341
View	N314S1	10	2023-08-23	Y	20242418342
View	K378S1	6	2023-08-23	Y	20242418343
View	R225S1	32	2023-08-24	Y	20242418346
View	J131S1	261	2023-08-24	Y	20242418347
View	D390S1	39	2023-08-24	Y	20242418348

«««« «« «12345» »» »»»»

Details License No. Bus No. Inspection Date Initial Approval Reexam Approval Approval No.


View	Y958S1	14	2023-08-24	Y		20242418349
View	V881S1	3	2023-08-24	Y		20242418350

«««« «« «12345»»»»»»»»

Back



STATE OF NEW JERSEY
MOTOR VEHICLE COMMISSION



School Bus Inspection Reporting System

Company Name: LACEY TOWNSHIP BOARD OF EDUCATION

Address: 200 WESTERN BOULEVARD

City: LANOKA HARBOR

County: Ocean

Zip Code: 08734

School Bus Company Statistical Summary:

Initial Out of Service Failure Rate: 12%

Initial Inspection Passing Rate: 87%

Number of School Bus Inspection Report(s) Found: 58

Note: Click View to select the inspection report for the report card details.

Out of Service Rejections:

	Details	License No.	Bus No.	Inspection Date	Initial Approval	Reexam Approval	Approval No.
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							
51							
52							
53							
54							
55							
56							
57							
58							
59							
60							
61							
62							
63							
64							
65							
66							
67							
68							
69							
70							
71							
72							
73							
74							
75							
76							
77							
78							
79							
80							
81							
82							
83							
84							
85							
86							
87							
88							
89							
90							
91							
92							
93							
94							
95							
96							
97							
98							
99							

View	H189S1	S2	2023-08-22	N	Y	20242418328
View	M817S1	S7	2023-08-22	N	Y	20242418332
View	V880S1	4	2023-08-23	N	Y	20242418344
View	A617S1	48	2023-08-23	N	Y	20242418345
View	Y982S1	15	2023-08-25	N	Y	20242418361
View	Y983S1	16	2023-08-25	N	Y	20242418363

«««« «« «» »»» »»»»»»

30 Day Defect(s):

	Details	License No.	Bus No.	Inspection Date	Initial Approval	Reexam Approval	Approval No.
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							
51							
52							
53							
54							
55							
56							
57							
58							
59							
60							
61							
62							
63							
64							
65							
66							
67							
68							
69							
70							
71							
72							
73							
74							
75							
76							
77							
78							
79							
80							
81							
82							
83							
84							
85							
86							
87							
88							
89							
90							
91							
92							
93							
94							
95							
96							
97							
98							
99							

View	A111S1	S3	2023-08-25	N	Pending for Reexam
------	--------	----	------------	---	--------------------

«««« «« « » »» »»»»»

Initial Approvals:

	Details	License No.	Bus No.	Inspection Date	Initial Approval	Reexam Approval	Approval No.
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							
51							
52							
53							
54							
55							
56							
57							
58							
59							
60							
61							
62							
63							
64							
65							
66							
67							
68							
69							
70							
71							
72							
73							
74							
75							
76							
77							
78							
79							
80							
81							
82							
83							
84							
85							
86							
87							
88							
89							
90							
91							
92							
93							
94							
95							
96							
97							
98							
99							

View	T231S1	21	2023-08-24	Y	20242418351
View	K591S1	30	2023-08-24	Y	20242418353
View	D481S1	25	2023-08-24	Y	20242418354
View	D469S1	49	2023-08-24	Y	20242418355
View	A112S1	47	2023-08-24	Y	20242418356
View	R226S1	33	2023-08-24	Y	20242418357
View	E315S1	51L	2023-08-25	Y	20242418358
View	S2V405	T1	2023-08-25	Y	20242418359

«««« «« «12345» »» »»»»»»

Details	License No.	Bus No.	Inspection Date	Initial Approval	Reexam Approval	Approval No.
View	N437S1	38	2023-08-25	Y		20242418360
View	N435S1	36	2023-08-25	Y		20242418362

«««« «« «12345» »» »»»»

Back

STATE OF NEW JERSEY
MOTOR VEHICLE COMMISSION

School Bus Inspection Reporting System

Company Name: LACEY TOWNSHIP BOARD OF EDUCATION

Address: 200 WESTERN BOULEVARD

City: LANOKA HARBOR

County: Ocean

Zip Code: 08734

School Bus Company Statistical Summary:

Initial Out of Service Failure Rate: 12%

Initial Inspection Passing Rate: 87%

Number of School Bus Inspection Report(s) Found: 58

Note: Click View to select the inspection report for the report card details.

Out of Service Rejections:

[illegible]

View	H189S1	S2	2023-08-22	N	Y	20242418328
View	M817S1	S7	2023-08-22	N	Y	20242418332
View	V880S1	4	2023-08-23	N	Y	20242418344
View	A617S1	48	2023-08-23	N	Y	20242418345
View	Y982S1	15	2023-08-25	N	Y	20242418361
View	Y983S1	16	2023-08-25	N	Y	20242418363

« « « « « « « » » » » » » » » » »

30 Day Defect(s):

[illegible]

View	A111S1	S3	2023-08-25	N	Pending for Reexam
----------------------	--------	----	------------	---	--------------------

««««« ««« «» »»» »»»»»»»»»»»»

Initial Approvals:

[illegible]

View	N436S1	37	2023-08-25	Y	20242418364
View	R227S1	34	2023-08-25	Y	20242418365
View	D391S1	40	2023-08-25	Y	20242418366
View	SPEC	43	2023-08-31	Y	20242417538
View	SPEC	5	2023-08-31	Y	20242417539

«««« «« «12345» »» »»»»»»

back