


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

D1 STATEMENT: D1 stated he was driving south on Beekman Rd when he was encountered by a deer crossing the road. He then made a sharp right turn onto Rachel Court to avoid colliding with the deer. Upon attempting to make a right turn, he ran off the road left and crashed into parked motor vehicle bearing NJ Registration: R23KDK. I observed V1 was completely disabled. It is unknown on the extent of the damage under the vehicle, but I observed a broken left front tire and parts from V1 in the surrounding area. No injuries were reported at this time. No deer was found on scene.

Crash investigation: Upon walking to the centerline on Beekman Drive, I observed an unbroken tire mark which remained unbroken until the curb on Rachel Court. I observed no deer in the area. The damage observed to Vehicle 2 was only the front plate, bumper and possible paint damage.

An attempt to contact the registered owner of V2 was made, but yielded in no results.

Conclusion: Upon the completion of crash investigation, it was determined that D1 caused the crash due to carelessly driving V1 on Beekman Rd and Rachel Court.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Parra, Julio	270	Raics, James	177	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: 5 Case No: 23051150

144. Crash Diagram (NOT TO SCALE)

