


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 STRUCK V2 DURING LEFT-TURN.

D1 STATED V1 WAS AT THE STOP SIGN, IN WHICH D1 PROCEEDED TO MAKE A LEFT-TURN, WHICH RESULTED IN V1 COLLIDING INTO V2.

D2 STATED V2 WAS TRAVELING STRAIGHT WHEN V1 SUDDENLY MADE A LEFT-TURN, WHICH RESULTED IN V1 COLLIDING INTO V2.

BASED ON THE STATEMENTS GIVEN AND MY OBSERVATIONS, V1 CAUSED THE MVA DUE TO FAILURE TO YIELD THE RIGHT OF WAY.


146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Simpson, Yasmin	254	Raics, James	177	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23051444

144. Crash Diagram (NOT TO SCALE)



Not To Scale