


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 backed into parked V2.

D1 advised she picked up her two children and began to back out of her parking spot to go home when she backed into parked V2. D1 stated she checked her rear-view camera and mirrors and believed she had enough room to back out, however she mis-judged the distance between her and the bus.

Previous driver of V2 advised she was parked in the bus line waiting for her to be called forward when V1 backed into her.

D1 caused the crash due to backing unsafely.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Meyer, Robert	236	Raics, James	177	☐ Pending ☒ Complete

**STATE OF NEW JERSEY
MOTOR VEHICLE CRASH DESCRIPTION**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23052059

1. Curry, Sonya

SCHOOL BUS

(full size)

1 DRIVER			DOOR →		
2	3	4		5	6
7	8	9		10	11
12	13	14		15	16
17	18	19		20	21
22	23	24		25	26
27	28	29		30	31
32	33	34		35	36
37	38	39		40	41
42	43	44		45	46
47	48	49		50	51
52	53			54	55

MINIBUS

1 DRIVER			DOOR →	
2	3		4	5
6	7		8	9
10	11		12	13
14	15		16	17

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01


Station: FTPD Case No: 23052059

144. Crash Diagram (NOT TO SCALE)

101 Mettlers Rd
Central Jersey College Prep



Not To Scale



P.O.I.

V2

