


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 WAS STOPPED WESTBOUND ON RT 518 BEHIND A COUPLE VEHICLES AT A RED LIGHT. V2 WAS TRAVELING WESTBOUND ON RT 518 AND STRUCK V1. D1 RELATED HE WAS STOPPED WHEN V2 STRUCK HIM. D2 RELATED HE BUMPED V1. INVESTIGATION REVEALED THE SAME.

Other Descriptions

02 - STRUCK STOPPED VEHICLE - Field 119a

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Mahon, Frank	158	Raics, James	177	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23052247

144. Crash Diagram (NOT TO SCALE)

