


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death	
	02	07	01	05	44	M	-	-	-	04	04	04	-	LIBRADO POCHECO 31 OAK STREET NEW BRUNSWICK NJ 08901	

144. Crash Diagram



145. Crash Description/Narrative

V1 WAS TRAVELING SOUTH ON JFK BLVD AND V2 WAS TRAVELING WEST ON HAMILTON STREET.

D1 STATED THAT SHE WAS DRIVING STRAIGHT IN THE STRAIGHT LANE, SHE HAD THE GREEN LIGHT SO SHE ASSUMED IT WAS CLEAR TO GO. D1 VEHICLE STRUCK V2 IN THE FRONT PASSENGER SIDE.

D2 STATED THAT SHE WAS TRAVELING WEST ON HAMILTON STREET IN THE MIDDLE LANE WHEN HER LIGHT WAS GREEN. SHE STATED THAT WHEN SHE GOT TO THE INTERSECTION, HER VEHICLE WAS STRUCK BY V1.

DURING THIS TRAFFIC INVESTIGATION, I WAS UNABLE TO FIND A CAUSE OF THIS CRASH DUE TO CONTRADICTING STATEMENTS AND NO WITNESSES ON LOCATION.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Judson, Tyrell	276	Ellington, Ryan	174	☒ Pending ☐ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23053312

144. Crash Diagram (NOT TO SCALE)

