


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

D1 advised as she was driving westbound on Easton Avenue in the right-hand lane when she observed V2 driving erratically. Suddenly V2 attempted to enter the lane she was in. At this time V2 struck V1 in the rear (driver's side).

V1 and V2 subsequently pulled over however D2 wanted to exchange information and not contact the police. D2 then got back into his vehicle and left the scene when D1 stated she contacted the police. D1 advised the driver of V2 was a male and there was also a female passenger in the vehicle.

While on scene, I checked the area for the suspect vehicle, witnesses, and anything of evidentiary value with negative results.

It was determined that V2 caused the accident by following too closely and improperly changing lanes.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Davis, Tabitha	258	Ellington, Ryan	174	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23053342

144. Crash Diagram (NOT TO SCALE)

