


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

D1 advised she did not strike any object. D1 advised she did not know where or when she struck an object. D1 advised she was travelling south-bound on Easton Ave and V1's tire came off. During my investigation, I observed tire marks from Willow Ave. to Demott Ln. However, there is no evidence of V1 striking any objects. During my investigation, it was revealed D1 was DWI and arrested for the same (reference IR 23054428, for further details)

It is not known where or when V1 hit the object that created the tire damage. I suspect that V1 struck a curb and would have caused the damage to the tire.

Other Descriptions

It is not known what D1 struck at this time. - Field 128

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Rountree, Marcus	278	Raics, James	177	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23054428

144. Crash Diagram (NOT TO SCALE)

