

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 WAS TRAVELING ON HAMILTON STREET IN THE RIGHT LANE. V2 WAS TRAVELING ON HAMILTON STREET IN THE RIGHT LANE. V1 STRUCK V2.

D1 TOLD ME HE DID NOT REALIZE HOW CLOSE HE WAS TO THE CAR IN FRONT OF HIM AND STRUCK THE VEHICLE IN THE REAR BUMPER.

D2 TOLD ME SHE WAS TRAVELING ON HAMILTON STREET WHEN SHE WAS REAR ENDED.

INVESTIGATION REVEALED V1 CAUSED THE CRASH IN THAT HE WAS FOLLOWING TOO CLOSE AND STRUCK V2.

****TRAILER INFO****
NJ REGISTRATION TYW-97R
D C N LNDSCP&HRDSCP LLC
1036 HOW LN
N BRUNSWICK NJ 08902
2022, HAW, LPT, TRL, BLK

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Sepulveda, Jeremy	243	Ellington, Ryan	174	☒ Pending ☐ Complete

Case No: 23054479

An aerial photograph of a road intersection. A vertical road runs through the center, with a yellow diagonal-striped median on its right side. A horizontal road crosses the vertical one at the bottom. A red location pin is placed at the intersection, with the text "Veronica Ave & Hamilton St" written above it. Two vehicles are shown on the vertical road, moving away from the intersection: a white car labeled "V2" and a grey truck labeled "V1" behind it. A red star is positioned between the two vehicles. To the left of the vertical road, there is a green lawn and a building with a red location pin and the text "hmed". A north arrow in the top right corner points towards the top right of the image. A red banner at the bottom right contains the text "Not To Scale".

Not To Scale