

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death	

144. Crash Diagram

145. Crash Description/Narrative

V1 REAR-ENDED V2.

D1 STATED V1 ATTEMPTED TO STOP IN TRAFFIC, IN WHICH V1 KEPT MOVING WHILE BRAKING. D1 STATED V1 MANUEVERED TO THE RIGHT TO AVOID COLLIDING INTO V2, IN WHICH V1 LANDED INTO A DITCH. LET IT BE NOTED THAT D1 STATED V1 DID NOT MAKE CONTACT WITH V2.

D2 STATED V2 WAS SLOWING DOWN DURING TRAFFIC, IN WHICH V1 DID MAKE CONTACT WITH V2, DUE TO D2 OBSERVING A MINOR SCUFF ON V2's BUMPER.

BASED ON THE STATEMENTS GIVEN AND MY OBSERVATIONS, V1 CAUSED THE MVA DUE TO UNSAFE SPEED FOR THE WEATHER CONDITIONS.



146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Simpson, Yasmin	254	Raics, James	177	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23054741

144. Crash Diagram (NOT TO SCALE)



Not To Scale