


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 AND V2 IMPACTED ON HAMILTON ST BY SHEVCHENCKO AVE.

D1 STATED THAT SHE WAS INITIALLY STOPPED FOR A STOPPED SCHOOL BUS. D1, WHILE THE SCHOOL BUS WAS STOPPED, MADE A LEFT INTO THE ABOVE PARKING LOT. WHILE MAKING A LEFT TURN INTO 803 HAMILTON ST WHEN V2 TURNED IN FRONT OF HER AND IMPACTED HER VEHICLE.

D2 STATED SHE WAS STOPPED FOR A SCHOOL BUS. SHE BEGAN TO MAKE A LEFT TURN AND V1 IMACTED HER VEHICLE SUDDENLY.

I OBSERVED FTPD STREET CAMERA FOOTAGE THAT SHOWED V1 ATTEMPTING TO PASS V2 ON THE LEFT OVER THE DOUBLE YELLOW LINE.

INVESTIGATION REVEALED THAT V1 WAS ILLEGALLY PASSING V2, RESULTING IN THE ABOVE IMPACT.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Boylan, James	241	Ellington, Ryan	174	☒ Pending ☐ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23054765

144. Crash Diagram (NOT TO SCALE)

