

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

Vehicle 2 was stopped in traffic, facing south on Route 27.

Vehicle 1 was traveling south on Route 27, directly behind Vehicle 2.

Vehicle 1 then crashed into the rear of Vehicle 2.

Driver of Vehicle 2 stated he was stopped in traffic and was struck by Vehicle 1.

Driver of Vehicle 1 stated he attempted to brake but was unable to fully stop prior to the crash.

The investigation revealed that Vehicle 1 crashed into the rear of Vehicle 2 by following too closely.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Long, Christopher	253	Raics, James	177	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD

Case No: 23054896

144. Crash Diagram (NOT TO SCALE)

