


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

Veh #1 was parked on the grass facing West in the grass of 500 Elizabeth Ave (Franklin High School) after responding a fight call at that location. Upon clearing the call Veh #1 struck a fire hydrant on the rear passenger side door. Driver #1 stated he parked on the grass while responding to a fight call. When he cleared the call, he returned to his vehicle and when he drove the vehicle, he cut the wheel to get back on the roadway. While doing so he side swiped a fire hydrant that he did not know was there.

Accident investigation revealed veh #1 struck the fire hydrant due to driver inattention.

Other Descriptions

- 01 - Failed to observe fire hydrant - Field 118a
- 01 - SELF-INSURED - Field 25

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Livingston, Richard	198	Ellington, Ryan	174	☒ Pending ☐ Complete


**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: Area 4 Case No: 23054384

144. Crash Diagram (NOT TO SCALE)

Parking Lot
500 Elizabeth Ave
Franklin High School



Not To Scale