

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

On Wednesday, September 27, 2023, I responded to a crash on Canal Road by Bulter Road. At the time of the crash, the weather was dry, clear and the road surface was dry.

Unit 1, Vehicle - White Tesla Model S, Going Straight Ahead

Driver #1 stated he struck a Pothole on Canal Rd which caused some mechanically/steering issues to his vehicle.

Investigation reveals there was a huge Pothole on the shoulder of Canal Road by Bulter Road. V#1 veered over the fog line and struck the Pothole causing damage to his front right tire and making it difficult to steer. D#1 stated there was traffic traveling north bound which caused him to keep as far right as possible to avoid colliding with them.

Other Descriptions

- Pothole on shoulder - Field 128
- 01 - Pothole - Field 126a
- 01 - Pothole on shoulder - Field 118a
- 01 - Pothole - Field 126e

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Hartnett, Richard	168	Ellington, Ryan	174	☒ Pending ☐ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23056886

144. Crash Diagram (NOT TO SCALE)

