


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

On this date, D1 advised she was driving Southbound on Easton Avenue and struck a deer at the intersection of Easton Avenue and Demott Lane. D1 advised the deer was partially in the roadway and did not observe the deer in her path until she was near it. She stated she could not enter into the nearby lane because there were other vehicles in the left lane next to her.

The vehicle showed damage to the front right bumper of the vehicle which also contained blood and deer fur on the front grill of the vehicle.

Other Descriptions

01 - deer in roadway - Field 118a

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Davis, Tabitha	258	Ellington, Ryan	174	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23057203

144. Crash Diagram (NOT TO SCALE)

