


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 WAS TRAVELING NORTH ON SOUTH MIDDLEBUSH RD.

D1 STATED THAT HE WAS DRIVING THROUGH THE FLOOD WATER AND A CAR INFRONT OF HIM STOPPED SHORT FORCING HIM TO HIT HIS BRAKES EXTREMELY HARD. AFTER HE MOVED HIS CAR OUT OF THE FLOOD WATER, HIS VEHICLE DIED AND HE BELIEVES IT WAS BECAUSE WATER GOT INTO HIS EXHAUST PIPE.

NO FURTHER INFORMATION.

Other Descriptions

01 - FLOODED ROADWAY - Field 118a

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Judson, Tyrell	276	Ellington, Ryan	174	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23057307

144. Crash Diagram (NOT TO SCALE)

