

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 STRUCK V2 AT INTERSECTION.

D1 REPORTED WHILE AT THE STOP SIGN ON SKILLMAN LANE AND SOMERSET ST, V2 WAS TRAVELING SOUTH ON 27 AND STRUCK HIS VEHICLE. V1 SUSTAINED MINOR DAMAGE ON FRONT BUMPER.

D2 REPORTED WHILE TRAVELING SOUTH ON ROUTE 27, V1 WAS STOPPED AT STOP SIGN ON SKILLMANS LANE. D2 REPORTED V1 WAS SLOWLY GOING THROUGH THE STOP SIGN AND STRUCK HIM ON THE PASSENGER SIDE FRONT AND BACK DOOR.

INVESTIGATION REVEALED THE CRASH OCCURRED DUE TO D1 FAILING TO YIELD THE RIGHT OF WAY TO V2.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
McCluney, Carron	280	Raics, James	177	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FRANKLIN

Case No: 23057328

144. Crash Diagram (NOT TO SCALE)

